

MONTHLY OPERATING REPORT
May 2008

EXECUTIVE SUMMARY

There were no odor reports in the month of May.

Secondary #1 was repaired by Waterline Industries. When inspected this clarifier shows the same type of corrosion of the bolts. The bolts holding the plows were replaced as well as many others. The new bolts were coated and the clarifier returned to service.

A new drive chain was installed on secondary #2.

National Watermain was here and completed the annual camera work of 10,000 feet and cleaning of 42,000 feet.

The gardener was on site prior to Memorial Day to weed and mulch the gardens. The staff mowed the lawns and weedwacked the area to make the facility presentable for the Holiday.

The motor brake coil for the step screen was replaced. One of the electrical connectors broke off.

Contractors have been on site to repair spalling concrete and removal of old aeration gates prior to installation of new motorized gates.

In an effort to control odors in the gravity thickener we are adding sodium hypochlorite to the primary sludge feed line.

We have started thickening secondary sludge using the rotating sludge thickener (RST).