

Presentation of Findings

Town of Hull, Massachusetts

Table of Contents

Introduction

- Who is EMG?
- EMG's Observations
- EMG's Findings
- EMG's Replacement Reserves
- Terms to Know
- Facility Condition Index (FCI)

Executive Summary

- 5 Year Reserve Summary
- FCI Summary
- School Comparisons
- Facility Comparisons

Capital Planning / Priorities

- School Priorities
- Facility Priorities





Introduction

Who is EMG



Nationwide



Track Record



Offices

Scope of Services for Town of Hull



Facility Condition Assessment (FCA) with MEP Inventory




Asset Management Platform with Data Export to "SchoolDude"



Preventative Maintenance Plan

The FCA Process



Terms to Know

Expected Useful Life (EUL) Industry standard life expectancies.

Effective Age Assessors' professional opinion of an assets condition in terms of years as it relates to an asset's EUL.


Remaining Useful Life (RUL) Difference between the EUL of an asset and its assigned effective age.

Short term considerations Assets whose effective age has either reached or exceeded their industry accepted EULs.

Reserve Items A list of assets whose effective age has not yet attained their industry accepted EULs

Current Replacement Value (CRV) Researched value to rebuild a facility.

FCA - Critical Data Points





FCA – Typical Outputs

- Replacement Reserves
- Prioritization
- Systems and Conditions Table
- Facility Condition Index
- Capital Planning
- Work Completed

Sample Output - Replacement Reserves

×	placement Reserves Report																								
ile	ing Room																							- (i	(nms
																								ľ	,mg)
0.000	12016																	LL CONTRACTOR DE LA CON						-	
	Section ID Coef Description 2 ISSNS 81021 Teinite Impact Placeholder (Capiture Estimated Costs to Correct		en (EVC	EAge				EA S1.764.935.00				3017	2018 2	919 3020	2021 2022 202	79 2034	3125	2004	2027	3038 3029	2000	3014 3012 3033	2014 DW	honey	S1,794,935
				-				EA 2152,500.00						\$152,500			1152 500				1152.500				\$610,00E
-				-	9 19				\$135,196					-			-								\$135,550
4	상			40	8 42				\$121.525																\$121,126
8.5	357193 E3019 Plumpare Milipaton - Roof and Enteror Trial Retrofiting			0	0 104	00 Pa	ne :		5635,100																\$635,190
84	356546 82011 Stucco, Parillel Enterior, 5-2 Stories, Repair				45	1 14		F \$18.20	\$8,226	\$8,200															\$6,296
14	25/246 82011 Exteror Had Part 3-2 Stores, Prep & Faet	- 11		8 3	965	E Fai	. 1	# 12.67	\$25.916			525,916						- 1	125.916						\$61,612
64	250104 82231 Metal Skiling, Metor-Operated, Enteror Door, Replace	30		20 9	2	10		A \$11,307.69	122,615							122,415									922,015
44	356185 \$2002 Shed Exterior Door, Anglace	.25		20 5	3	Fal		A 2950.12	52,850					32,816											\$2,810
40	556 CS CSF12 Gypsum Brand Planter Shriat, Interior Vital, Prep & Part	. 10		7 3	1480	f de	. 5	21.60	126,899				526,800							\$26,860					\$53,760
4.0	350186 C3012 Hidgosper, Interior Hall Front. Replace	- 15			1500	1 m	. 5	12.02	\$3,650		33,030											13,000			\$5,050
1.0	25ETEZ C3524 Ceramo 76e Flooring, Repair				1300	Fate	51	52490	\$52,579	\$52,579															\$52,379
	SMITH CROSS Guarry Tile Flooring, Replace	56	4	2	5800	False	0.0	\$16.10	386,162			104,162													\$60,000
	256201 C3024 Ceramic Tile Fisoring Repair	0	0		400	Fine	9	\$24.90	\$3,500	53,560															\$9,000
	100100 C3025 Carpet, Standard Commercial Medium Traffic, Replace	10		1	4600	Falce	58	112.62	358,672		558.972							358.972							\$117,344
	SENSZ C3032 Accounts at Tile Ceiling, Regisce	26	.20		13000	False	58	54.60	\$82,400	562,400															942,400
- 1	ISSN ESDS2 Package Unit, Single Zune, 8 to 10 Ton, Replace	15				Fee	EA	212.534.44	218.554							218.55	4								\$18,55
	ISSS D3052 Package Unit. Single Zone. 5 Ton. Replace	15	16	1	1	False	64	\$11,239.29	\$11,239		\$11,230											\$11,239			\$20,47
35	SN 03052 Package Unit Single Zone, 16 to 20 Ton, Replace	25			1	False	EA	556,777.37	536,777							\$56.77	7								\$36,77
	134 ID3052 Package Unit. Single Zone. 21 to 25 Ton. Replace	15	15		1	far	ga.	\$44,377.70	544,579	\$44,376											544	378			\$66,71
	11 D3052 Package Unit Single Zone, 5 Ton, Replace	15			2	False	EA		122.479							522.6	*				-510				520.4
	If £5052 Package Unit, Single Zone, 3 Yor, Replace	15	14			Faine	64	39.671.60	\$9.872		39.672					-						\$8,672			\$19.7
		15	-			False	64	59,671.90	19.672							19.6									55
	* D3052 Package Unit. Single Zone, 3 Tan, Replace			-			1277	407075700	A 100 A 100 A							24,6	4								
	D2023 Domestic Buller, Gas. 200 to 500 MBH, Replace	22	20	-		False	EA		120,417			\$28,417													531
		29	11		1	Falon	EA.		\$2,141							52,1	41								
356542	D2023 Violer Mealer, Gae, Residential, S1 to 126 GAL, Replace	10	8	2	1	Filte.	EA	\$3,526.63	\$3,529			\$1.529							\$3.5	129					
56208	12033 Floor Drain, Replace	10	29		6	False	£A.	\$406.91	\$2,441		\$2,441														
14528 8	4001 Killchen Fire Suppression System (CO2), Replace	5	6 1		1	False	EA	\$4,447.10	54,447							54.6	47								
6541 0	1037 Pire Allarm Control Planet, Multipless, Replace 1	1	8 7			False	6A	54,284.35	54,294						\$4,264										
,									1	2,366,144 \$	85,505 \$	137,964	\$24,880	\$0 \$155,360	50 54,284	\$0 \$116,0	85 \$152,0	00 518,5	172 529.	445 \$26,650	50 30	96,878 \$24,545	\$0	\$0. 50	\$3,0
NO.										50	50	50	\$0	10 10	\$0 60	50	\$0	\$0	\$0.	\$0 \$1	1 50	50 50	10	\$0. 50	
	don, compounded annually)								-	anno di Sulle			-	and the con-	1	Military	10	Topico.	100	1	1	06.729 \$38.7W	1		

FCA Output - Prioritization

- Building (100% weight)
- Component / System (10%)
- Plan Type (1,000%)
- Remaining Useful Life (1%)

Current Facility Weights - Priorities

Location	Priority
Jacobs Elementary School	10 - Highest ▼
Hull High School	10 - Highest ▼
Memorial Middle School	10 - Highest ▼
Village Fire Station	8
Fire Department	8
Town Hall/Police Station	7
Public Library	6 ▼
Veterans/Senior Center	4 ▼
Highway Department	2

FCA Output - Facility Condition Index



Allows us to derive a single qualitative figure from a much larger and complex matrix of quantitative data.

A Single Number – FCI

Short term considerations

Assessors' Objectiveness

Current Replacement Value (CRV)

(Facility Needs) / CRV = FCI (%)



Facility Condition Index (FCI)

What is the FCI percentage really telling us?





Executive Summary

Reserve Summary – 5 Year

Schools	CRV	\$/SF	Current	3 yr	5 yr
Jacobs Elementary School	\$28,665,000	\$245	\$1,556	\$44,526	\$132,757
Memorial Middle School	\$15,182,070	\$230	\$1,400,785	\$2,428,431	\$2,657,838
Hull High School	\$18,867,375	\$225	\$2,825,931	\$3,603,226	\$3,603,226
Town Facilities					
Veterans/Senior Center	\$872,280	\$180	\$9,384	\$37,040	\$50,036
Fire Department	\$1,224,015	\$195	\$75,485	\$84,363	\$112,252
Public Library	\$997,710	\$210	\$235,432	\$260,822	\$299,317
Village Fire Station	\$521,040	\$195	\$149,252	\$193,912	\$196,129
Highway Departments	\$1,936,900	\$175	\$589,236	\$646,954	\$653,280
Town Hall/Police Station	\$5,613,520	\$220	\$4,315,871	\$4,315,871	\$4,432,085


FCI Summary

Schools	CRV	Current	3 Yr (2020)	5 Yr (2022)
Jacobs Elementary School	\$28,665,000	0.0%	0.2%	0.5%
Memorial Middle School	\$15,182,070	9.2%	16.0%	17.5%
Hull High School	\$18,867,375	15.0%	19.1%	19.1%
Town Facilities				
Veterans/Senior Center	\$872,280	1.1%	4.2%	5.7%
Fire Department	\$1,224,015	6.2%	6.9%	9.2%
Public Library	\$997,710	23.6%	26.1%	30.0%
Village Fire Station	\$521,040	28.6%	37.2%	37.6%
Highway Departments	\$1,936,900	30.4%	33.4%	33.7%
Town Hall/Police Station	\$5,613,520	76.9%	76.9%	79.0%






School Comparisons – Needs and CRVs







School Comparisons – FCI




School Comparisons – 3 Year FCI



School Comparisons – 5 Year FCI




Facility Comparisons – Needs and CRVs







Facility Comparisons-FCI



Facility Comparisons – 3 Year FCI



Facility Comparisons – 5 Year FCI





Capital Planning / Priorities

Top 10 School Priorities

<u>ID</u>	<u>Location</u>	<u>UF</u> <u>Code</u>	<u>Description</u>	<u>Lifespan</u>	Raw Score	Condition	<u>First</u> <u>Replacement</u>	<u>Plan Type</u>	Quantity	<u>Unit</u>	Cost
455457	Hull High School	G2012	Roadways, Asphalt Pavement, Full Depth (includes sub-base), Repair	(No Lifespan)	89.64	Poor	2017	Safety	22,500	SF	\$156,150
455455	Hull High School	G2012	Roadways, Asphalt Pavement, Full Depth (includes sub-base), Repair	(No Lifespan)	89.64	Poor	2017	Safety	32,000	SF	\$222,080
461771	Memorial Middle School	B1015	Exterior Stairs, Concrete, Repair	(No Lifespan)	80.98	Poor	2017	Performance/Integrity	1,000	SF	\$3,875
461744	Memorial Middle School	B3011	Roof, Slate, Replace	50	80.96	Poor	2017	Performance/Integrity	19,000	SF	\$1,235,000
455498	Hull High School	B2011	Exterior Wall, Brick or Brick Veneer, 1-2 Stories, Repoint	25	80.95	Poor	2017	Performance/Integrity	47,860	SF	\$1,975,785
455505	Hull High School	B2011	Exterior Wall, Joint Expansion Cover/Assembly up to 2", Aluminum, Remove & Replace	20	80.94	Poor	2017	Performance/Integrity	200	LF	\$7,660
455509	Hull High School	B2011	Exterior Wall, Joint Caulking 0" to 1/2", 3+ Stories, Remove & Replace	10	80.90	Poor	2017	Performance/Integrity	15,500	LF	\$47,895
461774	Memorial Middle School	B2011	Exterior Wall, Joint Caulking 1/2" to 1", 3+ Stories, Remove & Replace	10	80.90	Poor	2017	Performance/Integrity	15,000	LF	\$84,450
455486	Hull High School	D5022	Metal Halide Lighting Fixture, Wall Mount, 150 W, Replace	20	80.76	Poor	2017	Performance/Integrity	18	EA	\$12,212




Top 10 Town Facility Priorities

<u>ID</u>	<u>Location</u>	<u>UF</u> <u>Code</u>	<u>Description</u>	<u>Lifespan</u>	Raw Score	Condition	First Replacement	<u>Plan Type</u>	Quantity	<u>Unit</u>	Cost
465210	Fire Department	B1015	Exterior Stairs, Metal, Replace	40	88.10	NA	2017	Safety	100	SF	\$4,453
469884	Highway Department	D5037	Fire Alarm System, Multi-Family, Upgrade/Install	20	82.46	NA	2017	Safety	11,000	SF	\$24,067
469119	Highway Department	D3042	Exhaust Fan, Roof Mounted, 10,001 to 20,000 CFM, Replace	15	82.45	NA	2017	Safety	1	EA	\$11,572
469104	Highway Department	P000X	Engineer, Fire Protection, System, Evaluate/Report	(No Lifespan)	82.05	NA	2017	Safety	1	EA	\$6,958
464920	Village Fire Station	B3011	Roof, Asphalt Shingle Premium Grade, Replace	30	79.17	Poor	2017	Performance/Integrity	2,200	SF	\$11,088
464919	Village Fire Station	B2011	Exterior Wall, Vinyl Siding, 1-2 Stories, Replace	25	79.16	Poor	2017	Performance/Integrity	3,200	SF	\$67,200
464939	Village Fire Station	B1015	Exterior Stairs, Wood, Replace	15	79.14	Poor	2017	Performance/Integrity	100	SF	\$3,693
464923	Village Fire Station	B2021	Window, Wood 12 SF, 1-2 Stories, Replace	30	78.99	Poor	2017	Performance/Integrity	25	EA	\$17,997
464925	Village Fire Station	D5092	Generator, Gas or Gasoline, 7 to 9 kW, Replace	25	78.99	Poor	2017	Performance/Integrity	1	EA	\$15,450
464928	Village Fire Station	B3016	Gutters & Downspouts, Aluminum w/ Fittings, Replace	10	78.94	Poor	2017	Performance/Integrity	200	LF	\$1,674


Minimum Funding Req.to Retain Fair Cond.

Deferred all Costs thru Year 3




Minimum Funding Req. to Retain Fair Cond.


Deferred all Costs thru Year 5



Minimum Funding Required to Retain Fair Condition at Year 5







Thank you for viewing

If you have any questions, please contact **Edward Beeghly**, Asset Management Director with EMG at **EBeeghly@EMGCorp.com** or voice at 800.733.0660 ext. 7607