rices - AOS

Hull, Ma 02045-1313 Tel # 781-925-0906 Fax # 781-925-3056



MONTHLY OPERATING REPORT August 2012

EXECUTIVE SUMMARY

There was one odor report in the month of August.

Chemical feed, Ferrous Chloride, was set up at Station #3 and chemical feed was initiated.

Inland Waters was on site to clean station wetwells of grease and debris. Stations 1, A, 3, and 5 were cleaned.

Influent pump #5 has been removed from service to be rebuilt. The motor, drive shaft and cover have been sent to First Electric for rebuild of the motor, replacement of the shaft sleeve and machining of the cover to accept a mechanical seal. New pump bearings will be installed.

Station #1, pump #2 has been removed from service due to failure of the suction cover plate. A replacement plate has been ordered and a temporary patch has been installed to have two pumps available in the case of heavy rains. A new mechanical seal will be installed.

A Hydrogen Sulfide monitoring station has been set up at Station #6 to allow for monitoring of sulfide levels in the interceptor.

The blend box motor wiring failed but a second set of conductors was available in the conduit and has been utilized.

We continue to run the rotating sludge thickener to thicken the secondary sludge.