



MONTHLY OPERATING REPORT November 2012

EXECUTIVE SUMMARY

Fax # 781-925-3056

There were two odor reports in the month of November.

Primary clarifier #2 had a leaking lip seal replaced. The drive unit is no longer leaking oil and the clarifier has been put on line. Primary clarifier #1 has been taken off line.

The boiler system has been cleaned and repaired. The fire eye circuit had failed which would not allow the furnaces to run. That circuit has been repaired and the system is operating properly.

A new backflow preventer has been installed on the potable water feed line to the building. The old unit had not passed its test, a rebuild kit was used to repair the backflow device and the unit would still not pass testing so the old unit was replaced and the new unit passed testing.

Influent pump #1 was found to have a bad VFD control board. A new board has been ordered. The pump can be used in VFD bypass mode where it operates on line power so is either on or off.

The bisulfite pump for chlorine removal has been repaired. The peristaltic tube was replaced.

Circulator pumps for the unit heaters to the shop and garage have been replaced.