United Water - AOS 1111 Nantasket Avenue Hull, Ma 02045-1313 Tel # 781-925-0906 Fax # 781-925-3056



MONTHLY OPERATING REPORT January 2010

EXECUTIVE SUMMARY

There were no odor reports in the month of January.

Station 4, pump #2 was replaced. A new rotating assembly had been purchased through capital funds. A new mechanical seal was also installed.

Station 3, pump #1 has a hole in its suction cover. A repair has been done but a new replacement piece will be ordered. The internal wear ring cut a slice in the suction cover casting.

The step screen conveyor jammed. We cleaned out the material jamming the conveyor but it still would not run. Our electrician was called in and he found a loose wire in the control cabinet which when connected started the conveyor.

A collapsed sewer line was repaired by Hub Construction on Kenton Ave and the line was cameraed to assure there was no debris in the line.

A blockage was cleared on Atlantic Ave. from a heavy build up of grease in the line.

Annual fire extinguisher inspection was performed by Plymouth County Fire Extinguisher Service.