United Water - AOS 1111 Nantasket Avenue Hull, Ma 02045-1313 Tel # 781-925-0906 Fax # 781-925-3056



MONTHLY OPERATING REPORT January 2012

EXECUTIVE SUMMARY

There were no odor reports in the month of January.

Plant Water pump #1suction valve has been replaced.

Station #9 has been returned to United Water as the pipe bursting project has been completed.

#1 RAS pump motor has been rebuilt and reinstalled. Pump is now available for operation.

Our electrical contractor, Pioneer Electric has been on site to address several issues. Station #4 soft starts were not ramping the pumps properly, the controls were reprogrammed to give proper ramp up speeds. Station A had a grounding problem. The grounds were tied to the neutral buss so there was a chance that electricity could backfeed. A dedicated ground buss has been installed. Station #9 needs to have wiring replaced to provide for lights in the lowest level, the chamber where the pumps are located.

Plymouth County Fire Extinguisher Service has been on site and performed annual fire extinguisher inspections.

The secondary gallery has had new RAS discharge piping and valves installed. The integrity of the piping was in question due to its age and the valves were inoperable so we were unable to isolate the RAS pumps for repair. An estimate for replacing all RAS piping had been obtained, the cost was high so it was decided to break the job into smaller pieces, this being the first step. We will continue to work with our contractor to continue replacing pipe and valves.