





woodardcurran.com

COMMITMENT & INTEGRITY DRIVE RESULTS

HULL WATER POLLUTION CONTROL FACILITY

FEBUARY 2023

MONTHLY OPERATING REPORT



NPDES NO. MA0101231

Table of Contents

1	Ex	ecutive Summary
2	Flo	ows and Loadings4
	Avera	age effluent monthly flows — 2+ year comparison5
	Two	Month Summary of Rainfall and the Influence on Effluent Flows6
3	Co	mpliance7
4	Ke	y Performance Indicators
6	Ma	aintenance Summary
	a.	Tasks Completed this Month
	b.	Asset Management Accounts17
5		Asset Management Accounts17 fety
5 6	Sa	
-	Sa Sta	fety18
6	Sa Sta	fety
6	Sa Sta Co	fety
6	Sa Sta Co a. b.	fety

1 EXECUTIVE SUMMARY

This Monthly Operating Report provides a summary of the pertinent information and activities that occurred at Hull WPCF during the month of February 2023.

- No lost-time incidents for the month of February.
- Continuing Covid-19 awareness- adhering to W&C, Town of Hull, and CDC guidelines and sharing any protocol updates.
- There were 136 effluent samples taken in February.
- There was one alarm call afterhours that required a response by W&C staff.
- The Asset Management Accounts summaries for contract year #8 is attached- latest revision date is 2/16/23.
- There were 7 calls from residents for E-One grinder pump issues.
- W&C's O&M continued its efforts to support the various ongoing engineering projects and upgrades at the plant- see the projects section.
- The weekly Bio Bot Covid-19 wastewater sampling & monitoring program continued with W&C staff assisting Brian Kiley of the HSD when needed.

Mike Sullivan – Plant Manager Town of Hull WPCF 3/28//2023

Woodard & Curran strives to deliver a high-quality operations service and is responsive to our customers concerns. Please feel free to request any modifications to the format or content of this report.

2 FLOWS AND LOADINGS




Average Daily Flows and Loadings for *February*

Month / Voor	Eff Flow	Inf Flow	Inf BOD	Inf TSS	Eff BOD	EFF TSS
Month / Year	MGD	MDG	MDG LBS		LBS	LBS
Feb '21	1.55	1.79	2,888.35	2,888.35 3,786.84		299.77
Feb '22	1.86	1.88	1,372.10	1,571.40	71.37	146.41
Feb '23	1.37	1.45	1,327.96	1,761.78	59.29	93.47


* On-Going -the existing influent flow meters are strap-on doppler flow meters, and the existing pipe condition prevents getting a strong signal. An area velocity meter in the aeration tank inlet channel is used as well as the headworks influent Parshall Flume meter to monitor influent flows. All reported loadings are based on the effluent flow meter [new mag meter April 2021]. All meters are tied into the Scada system so that influent flows can be monitored.

AVERAGE EFFLUENT MONTHLY FLOWS – 2+ YEAR COMPARISON

The monthly average flow for February was 1.37 MGD, less than 2.35 MGD in January. Total precipitation for February was 3.06 inches, well less than January's 7.62 inches, and had no impact on the plant's process conditions. The graph below shows the 2-plus year summary of the monthly average flows.



TWO MONTH SUMMARY OF RAINFALL AND THE INFLUENCE ON EFFLUENT FLOWS



This graph shows the days where precipitation occurred [rainfall] [Blue Peaks].


Hull Water Pollution Control Facility Monthly Operating Report

3 COMPLIANCE



Plant Effluent


• The plant process conditions through February were steady.




Monthly Process Summary graphs from power BI: December- January-February 2023

Hull Water Pollution Control Facility Monthly Operating Report

SECONDARY PROCESSES – POWER BI GRAPHS



2-month period ending on 2/28/2023.



Additional Power BI Graphs showing trends of various processes - 2/1/2022 - 2/28/2023.


4 KEY PERFORMANCE INDICATORS



				Perr	mit Comp	oliance						
	Parameter Info			Permit Requirements				Results				
Parameter	Hach WIMS Variable #	Units	Daily Max	Daily Min	Weekly Avg Max	Monthly Avg Max	Freq	Period Avg	Period Min	Period Max	# of Samples	# of Violations
EffTSS	104/999081	MG/L	50		45	30	1 X Week	7.9	4.8	12.5	4	0
Eff TSS	184	LBS		6)	1152	768	1 X Week	93.5	57.6	142.8	4	0
% TSS Rem	208	%		85		1	1 X Month	1	94.7	í.	1	0
Eff BOD	108	MG/L	50		45	30	1 X Week	5.0	4.2	6.0	4	0
Eff BOD	185	LBS			1152	768	1 X Week	59.3	57.6	62.0	4	0
% BOD Rem	207	%		85			1 X Month		95.5		1	0
Eff Chlorine	142	MG/L	1			0.7	3 X Day	0.21	0.00	0.68	84	0
Eff Fecal	111	#/100 ML	260			88	1 X Week	10.0	10.0	10.0	4	0
EffpH	136	SU	8.5	6.5			1X Daily	6.7	0.7	7.2	28	1
Enterococci	255	#/100 ML	276			35	1 X Week	12	10	20	4	0
									Totals		136	1

There were 136 effluent samples taken in February. NOTE- there was NO pH violation, rather there was an error in uploading recorded data- the pH on the day in question was 7.0, and not a .70 as recorded.

EFFLUENT COMPLIANCE POWER BI GRAPHS




Quality of the effluent was satisfactory, turbidity NTU levels were normal.

Sewage Gallons Treated vs Sludge Disposed

Month	Effluent Treated, MG	Sludge Disposed, Gals
February 2021	43.4	116,500
February 2022	52.2	86,000
February 2023	38.3	76,500


Hull Water Pollution Control Facility Monthly Operating Report



Additional Power BI graphs for sludge solids for 3-month period ending 2/28/2023.


The Bioxide system was on, but the feed rates were minimal, as normal seasonal temperatures were cooler. Monthly graphs are attached below, the daily average Bioxide use for February was about. 2-3 gallons per day.

 The "In-Pipe" bacteria containers in the collection system manholes were changed out on February 14th and 28th.



 <u>Slight changes</u> - Hydrogen sulfide (H2S) monitoring units were recording and trending on the odor scrubber. [inlet and outlet]. Increased scrubber fan speed slightly. See graph below:

Hull Water Pollution Control Facility Monthly Operating Report [pictured below: Scrubber trend and trending graphs for H2S levels recorded from the vapor link system cellular at XYZ Street/Nantasket Ave and Nantasket Ave/Water Street manholes.




XYZ – Nantasket Ave [closest to plant]

The odor data logging unit at XYZ monitoring the overall H2S levels close to the plant. From the graph, the daily pattern of H2S levels see a rise in the mid-afternoon until late evening/early AM.

Hull Water Pollution Control Facility Monthly Operating Report


Nantasket Ave/Water Street [at end of PS 3 force main and PS 4 discharge]

Pump station #3 - H2S is monitored at the end of the force main at the MH at Nantasket Ave & Water Street. Bioxide is added to allow excess nitrate in the sewage system to treat the additional H2S added from other parts the system – such as PS #4, contributions from lines feeding the interceptor - PS #5, PS #6, PS #9, Spinnaker Island, etc., all the way to the wastewater plant. H2S levels through February were minimal with generally mild temps for the winter, and adjustments for substantially less Bioxide feed were made.



Nantasket Ave

6 MAINTENANCE SUMMARY



The SEMS monthly work order summary for February is attached for review.

Hull Water Pollution Control Facility Monthly Operating Report

- On February 1st W&C staff assisted Phase 1 Tighe & Bond subcontractor Annese Electric with a Confined Space Entry. The CSE was required in order to get down into the grit pump room, beneath the headworks, to install a new MSA "GasGard" gas metering detection system.
- The water supply line for the toilet in the HSD trailer burst sometime in the morning hours of February 5th due to the frigid, below zero temps over that weekend. A local Serve-Pro crew was called in to clean up the trailer. It was learned in the course of this mishap that the water supply for the trailer actually comes from the Hull Lifesaving Museum next door. The water supply for the trailer will be changed to come from a metered line from inside the treatment plant.
- On February 9th a leak was discovered down in the lower level from newly installed piping, which was part of the Phase 1 HVAC upgrade. Upon investigation of the worsening leak, it was discovered that this pipe was a drain line for both the newly built lab and boiler rooms on the second floor. The two drain lines were wrongly plumbed into an old vent pipe, and not into the headworks, as per Phase 1 plans. After some two months of use the pipe was backed up enough and started leaking. W&C mechanics were able to re-route the drain piping properly to discharge into the headworks, as per the Phase 1 construction specs.
- On the 6th a technician from Mechanical Pump Services (Conn.) was onsite at PS # 6 to install and program a new Deragger II keypad unit on pump #2 de-ragging system.
- Two new mini cooling fans were installed for the #1 pump's VFD control at PS #9. A station pump by-pass had been set up using a portable 6 inch Thompson pump- in the event that case other working pump had a blockage or a failure as well.
- On February 24th W&C mechanics replaced the galvanized operating stems on several plant yard hydrants to a longer lasting stainless steel grade. These yard hydrants water source is the plant water system (PWS), which uses the treated final effluent, and not potable metered town water, which we would be charged for.
- On February 28 the plant's Godwin influent by-pass pump would not start for its monthly exercise running, due to a failed block heater. A local John Deer engine service provider was contacted, and they will also change the engine oil & coolant and perform any other factory recommended services.

A. ASSET MANAGEMENT ACCOUNTS

Please see the attached summary totals and planned expenditures for the Asset Management accounts for contract year (8). Most recent through 2/16/23



It is Woodard & Curran's policy to maintain a safe and healthy working environment for all employees and to comply with all applicable occupational health & safety regulations.

- No lost time incidents were reported for February.
- Monthly PM's emergency eyewash and shower inspections, fire extinguishers, and emergency lighting inspections completed.
- Monthly calibrations were performed on all MX4 & Max XT11 gas meters.
- On-going Covid-19 Pandemic awareness with daily review and as needed and keeping in contact with all onsite contractors regarding Hull and W&C covid-19 protocols.
- W&C's Pure Safety topic for February was machine guarding.
- The monthly W&C SPARKS safety meeting was held on February 22nd, including a review of W&C's monthly "Lessons Learned!"
- W&C's monthly safety inspection checklist for the plant was completed.
- All the First-Aid kits about the plant were restocked with supplies and 3 additional kits were purchased so that there is now an accessible kit First-Aid kit on every level of the operations building.

6 STAFF DEVELOPMENT

Training is an important part of any operation to ensure employee health and safety is assured, quality standards are supported, staff skills are improved, career opportunities become available, and higher productivity is achieved.

Listed is a general outline of training that the staff received over the course of the month:

- All staff completed W&C's monthly Pure Safety training and the staff's monthly safety meeting was held on February 22. Topics discussed were scaffolding, rigging & hoists, and reviewing the "near-miss" incidents occurring at all W&C projects in the January "Lessons Learned!"
- Regular, usually daily, operational updates and process control discussions, pump station operations, Dig Safes, and the HVAC construction project work scope ongoing at the plant. Daily safety briefings and Covid-19 protocol updates if necessary.

Staffing related items:

- Plant continued to have weekend coverage supplemented with part-time staffers Roger Boltrushek and Ryan Holman. in addition to Mike S, Luis B, Eric S, Dave W, and Joel T.
- O&M Specialists Paul Horigan and Jody St George continue to assist as needed with plant O&M projects.

7 COLLECTION SYSTEM

A. WET WELL CLEANING

The actual schedule for wet well cleaning: May 2022 to June 2023:

(X-Cleaned) - (Orange – Inspected) - (Green – See notes) - (blank – no work done)

	Pump Station								
Frequency of cleaning	A	1	3	4	5	6	9	D	
May, 2022									
June, 2022									
July, 2022									
Aug., 2022									
Sept. 2022									
Oct.,2022									
Nov, 2022									
Dec., 2023									
Jan., 2023									
Feb., 2023									
March 2023									
April 2023									


All pump stations except for Pump Station 3 and Station D have an aerator/mixer in the wet wells.

B. COLLECTION SYSTEM MAINTENANCE

Collection system work is being documented and tracked in Utility Cloud [UC] and a summarized report for September has been included as an attachment with the Monthly Operating Report.

Woodard & Curran assisted/conducted camera work and sewer system support in the Hull collection system at the following areas during the month of September. Ongoing backup and blockage call outs requiring an increase in labor and time to support. Below summarizes W&C's efforts at the various call out locations.

- There were seven calls for E-One Grinder pump service- see UC summary.
- There were two sewer backup calls from residents. Flushable cleaning wipes had built up on the shelf under the manhole at 173 Spring Street, causing the backup. W&C staff were able to shovel out a 5-gallon pail full of the wipes and debris- decent flow was restored. W&C staff will periodically check upon this problematic area and clean out the manhole shelfs as needed. The homeowner at 174 Samoset reported a backup in their home. W&C staff checked the up 7 downstream manholes and determined the blockage was actually in the house, a plumber was called upon to resolve their issue.
- Pump station emergency generator testing consists of weekly no load runs and monthly loaded runs.
- All Pump station wet wells were inspected in February- monthly station inspections are completed and combined with the monthly station PM's.
- Upload new or updated tie-cards to the UC as required.
- Dig-Safe mark outs are completed throughout the Town of Hull as needed to assist and facilitate scheduled and emergency gas repairs, broken water mains, roadway paving projects, and other residential and town projects. All are listed in the UC summary.




8 PROJECT MANAGEMENT & ADMINISTRATION



A. ON-GOING PROJECTS AND SUPPORT ITEMS

February updates:

- Phase 1 construction work in the operations building equipment is winding down and will be nearing completion in late March. Phase 2 Engineering contractor Barletta of Canton has been onsite periodically and are gearing up for an early April start.
- Plant Manager Mike S. and Assistant Plant Manager Joe B. are meeting weekly with John S. and Brian K. to discuss the Sewer Department operations, any treatment plant issues, the collection system, and any upcoming projects.



Totals

376

30

Corrective Maintenance

Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/2/23	17404	PS 3 Generator	Diagnose no start	Diagnosed no start. Battery dead. Charged battery and tried to start generator. Battery voltage dropped to ~8vdc. Sulfated battery. Installed new battery. Started fine. Verified function of trickle charger .3A. Checked charging system. Battery not charging. Inspected alternator. Found belt shredded. Installed new belt. Ran generator and verified charging system. 15vdc back to battery. Brought to operating temp and shut down. Put back into auto.	David Wilson	2/2/23	Completed
2/3/23	17405	PS Kholer Trailer Mounted Generator	Diagnose user interface failure	Inspected user interface and found the buttons not functional. Isolated display and removed from panel. Sealed unit is not serviceable. Got part number and supplied to tech from South Shore Generator. Parts ordered. Part came in. Tech onsite to install interface. Programming downloaded from unit. Isolated and removed part. Installed new part and programmed ECM. Verified program. Started generator and brought up to operating temp. Transferred station load to generator. No issues.	Outside Contractor	2/3/23	Completed
2/3/23	17406	Operations Building	Diagnose washing machine failure	Tested timer switch. Good. Tested lid switch. Fails to complete circuit. Isolated washing machine. Removed rear cover inspected wiring. Found a rats nest. Removed debris. Removed lid switch. Cleaned contacts and tested resistance. Good. Installed switch and verified operation. Installed cover. Cleaned under lid and ran a full cycle. Good overall.	David Wilson	2/3/23	Completed
2/3/23	17407	Plant water yard hydrants	Fabricated operating rods from 304 stainless steel.	JS purchsed material and cut to length. DW purchased 3/4 14 teeth for Rigid dye and threaded pipe.	David Wilson	2/3/23	Completed
2/9/23	17409	Grit Screw Classifier	Diagnose leak	Isolated grit classifier. Inspected for leaks. Found drain hose quick disconnect failed. Replaced old hose and fittings.	David Wilson	2/9/23	Completed
2/13/23	17410	PS 9 Generator	Block heater discharge hose failure.	Isolated block heater. Loosened hose clamps and removed hose. Inner hose liner separated and was stuck to fitting. Cut out risidual hose and installed new hose. Topped off coolant level and verified operation of block heater.	David Wilson	2/13/23	Completed
2/16/23	17411	Gravity Thickener 1	Gasket for the gearbox drain cap needs to be replaced	I made a new gasket and replaced the old one with that.	Luis Bello	2/16/23	Completed

Corrective Maintenance

Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/20/23	17412	22 - WW - sewers/pipes/force mains	Street backed up	Checked for flow in the street at the downstream manhole. Invert surcharged with paper towels and wipes. Fished onto shelf to get flowing. Removed enough debris to fil a 5 gallon bucket. Installed wrap o-ring between frame and cover.	David Wilson	2/20/23	Completed
2/23/23	17414	PS 1 Building	Install fall protection on mid level.	Drilled and tapped holes to install eyes on the end of the hand rails. Cut chains to fit. Attached chains with carabiners.	David Wilson	2/23/23	Completed
2/23/23	17413	PS 9 Building	Install fall protection on mid level.	Drilled and tapped holes to install eyes on the end of the hand rails. Cut chains to fit. Attached chains with carabiners.	David Wilson	2/23/23	Completed
2/24/23	17415	Plant water yard hydrants	Replace yard hydrant operating rod.	Isolated yard hydrant near SC#1. Seperated inner valve assembly. Installed stainless operating rod and reassembled hydrant. Returned to service.	David Wilson	2/24/23	Completed
2/24/23	17416	Plant water yard hydrants	Replace yard hydrant operating rod.	Isolated yard hydrant near SC#1. Seperated inner valve assembly. Installed stainless operating rod and reassembled hydrant. Returned to service.	David Wilson	2/24/23	Completed
2/24/23	17417	Plant water yard hydrants	Replace yard hydrant operating rod.	Isolated yard hydrant near SC#2. Seperated inner valve assembly. Installed stainless operating rod and reassembled hydrant. Returned to service.	David Wilson	2/24/23	Completed
2/24/23	17418	Plant water yard hydrants	Replace yard hydrant operating rod.	Isolated yard hydrant near SC#2. Seperated inner valve assembly. Installed stainless operating rod and reassembled hydrant. Returned to service.	David Wilson	2/24/23	Completed
2/24/23	17419	Plant water yard hydrants	Replace yard hydrant operating rod.	Isolated yard hydrant near AT#3. Seperated inner valve assembly. Installed stainless operating rod and reassembled hydrant. Returned to service.	David Wilson	2/24/23	Completed
2/24/23	17420	Plant water yard hydrants	Replace yard hydrant operating rod.	Isolated yard hydrant near AT#3. Seperated inner valve assembly. Installed stainless operating rod and reassembled hydrant. Returned to service.	David Wilson	2/24/23	Completed
2/24/23	17421	Plant water yard hydrants	Replace yard hydrant operating rod.	Isolated yard hydrant near AT#3. Seperated inner valve assembly. Installed stainless operating rod and reassembled hydrant. Returned to service.	David Wilson	2/24/23	Completed
2/24/23	17422	Plant water yard hydrants	Replace yard hydrant operating rod.	Isolated yard hydrant near AT#2. Seperated inner valve assembly. Installed stainless operating rod and reassembled hydrant. Returned to service.	David Wilson	2/24/23	Completed
2/24/23	17423	32 - WW Influent Process	Leaky breather valve from Influent pump 5	I cleaned the breather assembly	Luis Bello	2/24/23	Completed
2/27/23	17249	Emergency Lighting & exit signs	Stair waer lower level emergency light fail the test.		Luis Bello	1/13/23	Completed
2/27/23	13502	23 - WW Pump Stations	Bypassdrain at PS1, mid level, leaking from gasket		Jody St. George	2/18/21	Completed
2/27/23	13490	Building Flood Conrtol	Lower door hinge bearing is bad on door 7		Prev. Maint. Tablet	2/2/21	Completed
2/27/23	12831	PS A Piping and Valves	Discharge pressure gauges failed on both pumps.		David Wilson	10/7/20	Completed
2/27/23	12685	Waste Activated Sludge Pump 3	Pump seal failure		David Wilson	9/16/20	Completed

ispecti	ons						
Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/14/23	17075	Blower Room Exhaust Fan 1	Monthly operational inspection	Blower exhaust fan offline. Inspected components and brought online. Minimal vibration. No issues found.	David Wilson	2/1/23	Completed
2/14/23	17076	Blower Room Exhaust Fan 2	Monthly operational inspection	Blower exhaust fan offline. Inspected components and brought online. Minimal vibration. No issues found.	David Wilson	2/1/23	Completed
2/16/23	16936	Emergency Lighting & exit signs	Emergency Lighting Inspection - Monthly		Luis Bello	2/8/23	Completed
2/27/23	17034	Main Office	Monthly Safety Inspection		SEMS TABLET #2	2/1/23	Completed
2/27/23	17074	Blower Room Exhaust Fan 1	Monthly inspection		SEMS TABLET #2	2/1/23	Completed
2/27/23	16987	PS 1	PS #1 Inspection - Monthly		SEMS TABLET #2	2/2/23	Completed
2/27/23	16988	PS 3	PS #3 Inspection - Monthly		SEMS TABLET #2	2/2/23	Completed
2/27/23	16991	PS 4	PS #4 Inspection - Monthly		SEMS TABLET #2	2/2/23	Completed
2/27/23	16992	PS 5	PS #5 Inspection - Monthly		SEMS TABLET #2	2/2/23	Completed
2/27/23	16995	PS 6	PS #6 Inspection - Monthly		SEMS TABLET #2	2/2/23	Completed
2/27/23	16996	PS 9	PS #9 Inspection - Monthly		SEMS TABLET #2	2/2/23	Completed
2/27/23	16999	PSA	PS #A Inspection - Monthly		SEMS TABLET #2	2/2/23	Complete
2/27/23	16932	Eyewash Stations	WWTF Eyewash Inspection - Weekly		SEMS TABLET #2	2/5/23	Completed
2/27/23	16930	30 - WW Treatment Plant - General	Monthly H&S Inspection		Prev. Maint. Tablet	2/6/23	Completed
2/27/23	17031	Fire Extinguishers	WWTF Fire Extinguisher Inspections - Monthly		SEMS TABLET #2	2/6/23	Completed
2/27/23	17036	Truck 1 - 2010 Dodge Ram 1500	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	2/6/23	Completed
2/27/23	17046	Truck 2 - 2009 Chevy 2500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	2/6/23	Completed
2/27/23	17054	Truck 3 - 2015 Chevy 3500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	2/6/23	Complete
2/27/23	17055	Truck 4 - 2015 Nissan Frontier	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	2/6/23	Complete
2/27/23	16933	Eyewash Stations	WWTF Eyewash Inspection - Weekly		SEMS TABLET #2	2/12/23	Complete
2/27/23	17048	Universal waste area	Universal Waste Storage Area Inspection		SEMS TABLET #2	2/14/23	Complete
2/27/23	17047	Waste Oil Storage	Waste Oil Area Inspection		SEMS TABLET #2	2/14/23	Completed
2/27/23	16934	Eyewash Stations	WWTF Eyewash Inspection - Weekly		SEMS TABLET #2	2/19/23	Complete
2/27/23	16935	Eyewash Stations	WWTF Eyewash Inspection - Weekly		SEMS TABLET #2	2/26/23	Complete
2/27/23	17062	AST- Above Ground Storage tank for diesel fuel	Monthly Inspections of Tanks		SEMS TABLET #2	2/1/23	Complete
2/27/23	17062	AST- Above Ground Storage tank for diesel fuel	Monthly Inspections of Tanks		SEMS TABLET #2	2/1/23	Complete
2/27/23	16899	AST- Above Ground Storage tank for diesel fuel	Monthly Inspections of Tanks		SEMS TABLET #2	1/1/23	Complete

inspecti	ons						
Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/27/23	16784	Eyewash Stations	WWTF Eyewash Inspection - Weekly		SEMS TABLET #2	1/1/23	Completed
2/27/23	16913	Blower Room Exhaust Fan 1	Monthly inspection		SEMS TABLET #2	1/1/23	Completed
2/27/23	16870	Main Office	Monthly Safety Inspection		SEMS TABLET #2	1/1/23	Completed
2/27/23	16782	30 - WW Treatment Plant - General	Monthly H&S Inspection		Prev. Maint. Tablet	1/2/23	Completed
2/27/23	16872	Truck 1 - 2010 Dodge Ram 1500	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	1/2/23	Completed
2/27/23	16882	Truck 2 - 2009 Chevy 2500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	1/2/23	Completed
2/27/23	16891	Truck 4 - 2015 Nissan Frontier	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	1/2/23	Completed
2/27/23	16829	PS 1	PS #1 Inspection - Monthly		SEMS TABLET #2	1/5/23	Completed
2/27/23	16830	PS 3	PS #3 Inspection - Monthly		SEMS TABLET #2	1/5/23	Completed
2/27/23	16831	PS 4	PS #4 Inspection - Monthly		SEMS TABLET #2	1/5/23	Completed
2/27/23	16832	PS 5	PS #5 Inspection - Monthly		SEMS TABLET #2	1/5/23	Completed
2/27/23	16833	PS 6	PS #6 Inspection - Monthly		SEMS TABLET #2	1/5/23	Completed
2/27/23	16834	PS 9	PS #9 Inspection - Monthly		SEMS TABLET #2	1/5/23	Completed
2/27/23	16835	PS A	PS #A Inspection - Monthly		SEMS TABLET #2	1/5/23	Completed
2/27/23	16785	Eyewash Stations	WWTF Eyewash Inspection - Weekly		SEMS TABLET #2	1/8/23	Completed
2/27/23	16884	Universal waste area	Universal Waste Storage Area Inspection		SEMS TABLET #2	1/10/23	Completed
2/27/23	16883	Waste Oil Storage	Waste Oil Area Inspection		SEMS TABLET #2	1/10/23	Completed
2/27/23	16786	Eyewash Stations	WWTF Eyewash Inspection - Weekly		SEMS TABLET #2	1/15/23	Completed
2/27/23	16787	Eyewash Stations	WWTF Eyewash Inspection - Weekly		SEMS TABLET #2	1/22/23	Completed
2/27/23	16788	Eyewash Stations	WWTF Eyewash Inspection - Weekly		SEMS TABLET #2	1/29/23	Completed
2/27/23	16678	PS 4	PS #4 Inspection - Monthly		SEMS TABLET #2	12/1/22	Completed
2/27/23	16679	PS 5	PS #5 Inspection - Monthly		SEMS TABLET #2	12/1/22	Completed
2/27/23	16680	PS 6	PS #6 Inspection - Monthly		SEMS TABLET #2	12/1/22	Completed
2/27/23	16681	PS 9	PS #9 Inspection - Monthly		SEMS TABLET #2	12/1/22	Completed
2/27/23	16682	PS A	PS #A Inspection - Monthly		SEMS TABLET #2	12/1/22	Completed
2/27/23	16631	30 - WW Treatment Plant - General	Monthly H&S Inspection		Prev. Maint. Tablet	12/5/22	Completed
2/27/23	16719	Truck 1 - 2010 Dodge Ram 1500	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	12/5/22	Completed
2/27/23	16729	Truck 2 - 2009 Chevy 2500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	12/5/22	Completed

Inspecti	ons						
Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/27/23	16738	Truck 4 - 2015 Nissan Frontier	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	12/5/22	Completed
2/27/23	16732	Universal waste area	Universal Waste Storage Area Inspection		SEMS TABLET #2	12/13/22	Completed
2/27/23	16731	Waste Oil Storage	Waste Oil Area Inspection		SEMS TABLET #2	12/13/22	Completed
2/27/23	16511	PS 5	PS #5 Inspection - Monthly		SEMS TABLET #2	11/3/22	Completed
2/27/23	16514	PS 6	PS #6 Inspection - Monthly		SEMS TABLET #2	11/3/22	Completed
2/27/23	16515	PS 9	PS #9 Inspection - Monthly		SEMS TABLET #2	11/3/22	Completed
2/27/23	16518	PS A	PS #A Inspection - Monthly		SEMS TABLET #2	11/3/22	Completed
2/27/23	16457	30 - WW Treatment Plant - General	Monthly H&S Inspection		Prev. Maint. Tablet	11/7/22	Completed
2/27/23	16561	Truck 1 - 2010 Dodge Ram 1500	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	11/7/22	Completed
2/27/23	16574	Truck 2 - 2009 Chevy 2500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	11/7/22	Completed
2/27/23	16578	Universal waste area	Universal Waste Storage Area Inspection		SEMS TABLET #2	11/8/22	Completed
2/27/23	16577	Waste Oil Storage	Waste Oil Area Inspection		SEMS TABLET #2	11/8/22	Completed
2/27/23	16585	Truck 4 - 2015 Nissan Frontier	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	11/7/22	Completed
2/27/23	16429	Effluent Pump Rooom Wetwell	Annual cleaning and inspection		SEMS TABLET #2	10/1/22	Completed
2/27/23	16280	30 - WW Treatment Plant - General	Monthly H&S Inspection		Prev. Maint. Tablet	10/3/22	Completed
2/27/23	16373	Truck 1 - 2010 Dodge Ram 1500	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	10/3/22	Completed
2/27/23	16384	Truck 2 - 2009 Chevy 2500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	10/3/22	Completed
2/27/23	16385	Truck 2 - 2009 Chevy 2500 HD	ANNUAL STATE VEHICLE INSPECTION		SEMS TABLET #2	10/3/22	Completed
2/27/23	16386	Seconday Electrical Control Manhole	Inspect Secondary Electrical Manhole		SEMS TABLET #2	10/4/22	Completed
2/27/23	16399	Truck 4 - 2015 Nissan Frontier	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	10/3/22	Completed
2/27/23	16333	PS 5	PS #5 Inspection - Monthly		SEMS TABLET #2	10/6/22	Completed
2/27/23	16334	PS 6	PS #6 Inspection - Monthly		SEMS TABLET #2	10/6/22	Completed
2/27/23	16335	PS 9	PS #9 Inspection - Monthly		SEMS TABLET #2	10/6/22	Completed
2/27/23	16389	Universal waste area	Universal Waste Storage Area Inspection		SEMS TABLET #2	10/11/22	Completed
2/27/23	16388	Waste Oil Storage	Waste Oil Area Inspection		SEMS TABLET #2	10/11/22	Completed
2/27/23	16174	PS 5	PS #5 Inspection - Monthly		SEMS TABLET #2	9/1/22	Completed
2/27/23	16175	PS 6	PS #6 Inspection - Monthly		SEMS TABLET #2	9/1/22	Completed
2/27/23	16176	PS 9	PS #9 Inspection - Monthly		SEMS TABLET #2	9/1/22	Completed

inspecti	ons						
Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/27/23	16177	PS A	PS #A Inspection - Monthly		SEMS TABLET #2	9/1/22	Completed
2/27/23	16121	30 - WW Treatment Plant - General	Monthly H&S Inspection		Prev. Maint. Tablet	9/5/22	Completed
2/27/23	16214	Truck 1 - 2010 Dodge Ram 1500	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	9/5/22	Completed
2/27/23	16224	Truck 2 - 2009 Chevy 2500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	9/5/22	Completed
2/27/23	16232	Truck 4 - 2015 Nissan Frontier	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	9/5/22	Completed
2/27/23	16226	Universal waste area	Universal Waste Storage Area Inspection		SEMS TABLET #2	9/13/22	Completed
2/27/23	16225	Waste Oil Storage	Waste Oil Area Inspection		SEMS TABLET #2	9/13/22	Completed
2/27/23	16093	30 - WW Treatment Plant - General	Monthly H&S Inspection		Prev. Maint. Tablet	8/1/22	Completed
2/27/23	16043	Truck 1 - 2010 Dodge Ram 1500	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	8/1/22	Completed
2/27/23	16054	Truck 2 - 2009 Chevy 2500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	8/1/22	Completed
2/27/23	16064	Truck 4 - 2015 Nissan Frontier	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	8/1/22	Completed
2/27/23	15994	PS 5	PS #5 Inspection - Monthly		SEMS TABLET #2	8/4/22	Completed
2/27/23	15997	PS 6	PS #6 Inspection - Monthly		SEMS TABLET #2	8/4/22	Completed
2/27/23	15998	PS 9	PS #9 Inspection - Monthly		SEMS TABLET #2	8/4/22	Completed
2/27/23	16001	PS A	PS #A Inspection - Monthly		SEMS TABLET #2	8/4/22	Completed
2/27/23	16056	Universal waste area	Universal Waste Storage Area Inspection		SEMS TABLET #2	8/9/22	Completed
2/27/23	16056	Universal waste area	Universal Waste Storage Area Inspection		SEMS TABLET #2	8/9/22	Completed
2/27/23	16055	Waste Oil Storage	Waste Oil Area Inspection		SEMS TABLET #2	8/9/22	Completed
2/27/23	16092	30 - WW Treatment Plant - General	Monthly H&S Inspection		Prev. Maint. Tablet	7/4/22	Completed
2/27/23	15873	Truck 1 - 2010 Dodge Ram 1500	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	7/4/22	Completed
2/27/23	15883	Truck 2 - 2009 Chevy 2500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	7/4/22	Completed
2/27/23	15891	Truck 4 - 2015 Nissan Frontier	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	7/4/22	Completed
2/27/23	15834	PS 5	PS #5 Inspection - Monthly		SEMS TABLET #2	7/7/22	Completed
2/27/23	15835	PS 6	PS #6 Inspection - Monthly		SEMS TABLET #2	7/7/22	Completed
2/27/23	15836	PS 9	PS #9 Inspection - Monthly		SEMS TABLET #2	7/7/22	Completed
2/27/23	15837	PSA	PS #A Inspection - Monthly		SEMS TABLET #2	7/7/22	Completed
2/27/23	15885	Universal waste area	Universal Waste Storage Area Inspection		SEMS TABLET #2	7/12/22	Completed
2/27/23	15885	Universal waste area	Universal Waste Storage Area Inspection		SEMS TABLET #2	7/12/22	Completed

mopoour							
Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/27/23	15884	Waste Oil Storage	Waste Oil Area Inspection		SEMS TABLET #2	7/12/22	Completed
2/27/23	15672	PS 5	PS #5 Inspection - Monthly		SEMS TABLET #2	6/2/22	Completed
2/27/23	15673	PS 6	PS #6 Inspection - Monthly		SEMS TABLET #2	6/2/22	Completed
2/27/23	15674	PS 9	PS #9 Inspection - Monthly		SEMS TABLET #2	6/2/22	Completed
2/27/23	16091	30 - WW Treatment Plant - General	Monthly H&S Inspection		Prev. Maint. Tablet	6/6/22	Completed
2/27/23	15675	PSA	PS #A Inspection - Monthly		SEMS TABLET #2	6/2/22	Completed
2/27/23	15717	Truck 1 - 2010 Dodge Ram 1500	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	6/6/22	Completed
2/27/23	15727	Truck 2 - 2009 Chevy 2500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	6/6/22	Completed
2/27/23	15736	Truck 4 - 2015 Nissan Frontier	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	6/6/22	Completed
2/27/23	15730	Universal waste area	Universal Waste Storage Area Inspection		SEMS TABLET #2	6/14/22	Completed
2/27/23	15729	Waste Oil Storage	Waste Oil Area Inspection		SEMS TABLET #2	6/14/22	Completed
2/27/23	14426	Truck 3 - 2015 Chevy 3500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	10/4/21	Completed
2/27/23	14284	Truck 3 - 2015 Chevy 3500 HD	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	9/6/21	Completed
2/27/23	13931	Waste Oil Storage	Waste Oil Area Inspection		SEMS TABLET #2	7/13/21	Completed
2/27/23	13787	Truck 4 - 2015 Nissan Frontier	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	6/7/21	Completed
2/27/23	13629	Truck 4 - 2015 Nissan Frontier	Monthly vehicle inspection on do-Forms		SEMS TABLET #2	5/3/21	Completed

Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/1/23	16885	GasAlert Max XTII #2	monthly calibration	Calibrated 4 gas meter. No issues.	David Wilson	1/26/23	Completed
2/1/23	16878	Ventis MX4 #3 - 4 Gas	4 Gas Meter #3 Calibration - Monthly	Calibrated 4 gas meter. No issues.	David Wilson	1/26/23	Completed
2/1/23	16881	Ventis MX4 #6 - 4 Gas	4 Gas Meter #6 Calibration - Monthly	Calibrated 4 gas meter. No issues.	David Wilson	1/26/23	Completed
2/1/23	16880	Ventis MX4 #5 - 4 Gas	4 Gas Meter #5 Calibration - Monthly	Calibration failed. LEL sensor input on sensor board. Will be sent out.	David Wilson	1/26/23	Completed
2/1/23	16879	Ventis MX4 #4 - 4 Gas	4 Gas Meter #4 Calibration - Monthly	Calibrated 4 gas meter. No issues.	David Wilson	1/26/23	Completed
2/1/23	16877	Ventis MX4 #2 - 4 Gas	4 Gas Meter #2 Calibration - Monthly	Calibrated 4 gas meter. No issues.	David Wilson	1/26/23	Completed
2/2/23	16896	High level floats	Weekly High Float Alarm test		Luis Bello	1/29/23	Completed
2/2/23	16910	All Plant Gear box reducers	GEAR BOX MAINT - WEEKLY		Luis Bello	1/29/23	Completed
2/3/23	16980	Primary Sludge Pump 2	Monthly Check Pump Couplings		Luis Bello	2/1/23	Completed
2/3/23	16979	Primary Sludge Pump 1	Monthly Check Pump Couplings		Luis Bello	2/1/23	Completed

Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/6/23	16875	PS Kholer Trailer Mounted Generator	Generator Weekly - Test Run no load		David Wilson	1/23/23	Completed
2/6/23	17032	GasAlert Max XTII #1	4 gas meter calibration - monthly		David Wilson	2/1/23	Completed
2/6/23	17000	PS 1 Generator	PS #1 Generator Inspection and Load Test - Monthly		Eric Sutton	2/1/23	Completed
2/6/23	16876	PS Kholer Trailer Mounted Generator	Generator Weekly - Test Run no load		David Wilson	1/30/23	Completed
2/6/23	17001	PS 1 Generator	PS #1 Generator Inspection and Test - Weekly		Eric Sutton	2/1/23	Completed
2/6/23	17005	PS 3 Generator	PS #3 Generator Inspection and Test - Weekly		Eric Sutton	2/1/23	Completed
2/6/23	17009	PS 3 Generator	PS #3 Generator Inspection and Load Test - Monthly		Eric Sutton	2/1/23	Completed
2/6/23	17010	PS 4 Generator	PS #4 Generator Inspection and Load Test - Monthly		Eric Sutton	2/1/23	Completed
2/6/23	17011	PS 4 Generator	PS #4 Generator Inspection and Test - Weekly		David Wilson	2/1/23	Completed
2/6/23	17019	PS 5 Generator	PS #5 Generator Inspection and Load Test - Monthly		David Wilson	2/1/23	Completed
2/6/23	17029	PS 6 Generator	PS #5 Generator Inspection and Load Test - Monthly		Eric Sutton	2/1/23	Completed
2/6/23	17015	PS 5 Generator	PS #5 Generator Inspection and Test - Weekly		Eric Sutton	2/1/23	Completed
2/6/23	17020	PS 9 Generator	PS #9 Generator Inspection and Load Test - Monthly		Eric Sutton	2/1/23	Completed
2/6/23	17025	PS 6 Generator	PS #6 Generator Inspection and Test - Weekly		Eric Sutton	2/1/23	Completed
2/6/23	17021	PS 9 Generator	PS #9 Generator Inspection and Test - Weekly		David Wilson	2/1/23	Completed
2/6/23	17068	Generators "All Pump Station"	Generator - Monthly Load Test		Eric Sutton	2/5/23	Completed
2/6/23	17037	PS Kholer Trailer Mounted Generator	Generator - Monthly Load Test		David Wilson	2/5/23	Completed
2/6/23	16645	Aerated Grit Chamber	Grit Chamber Cleaning - Annual		Michael T. Sullivan	12/22/22	Completed
2/6/23	16946	Influent Sluice Isolation Gate	Weekly operate through full range		David Wilson	2/1/23	Completed
2/6/23	16973	RAS Pump 3	Monthly Check Pump Couplings	Inspected hubs and coupling.	David Wilson	2/1/23	Completed
2/6/23	16971	RAS Pump 2	RAS Pump #2 PM - Quarterly	LOTO of equipment. Exercised valves. Inspected hubs and coupling. Lubed upper and lower bearings of the motor and the pump. Inspected mechanical seal. Returned to service.	David Wilson	2/1/23	Completed
2/6/23	16970	RAS Pump 2	Monthly Check Pump Couplings	Inspected hubs and coupling.	David Wilson	2/1/23	Completed
2/6/23	16972	RAS Pump 3	RAS Pump #3 PM - Quarterly	LOTO of equipment. Exercised valves. Inspected hubs and coupling. Lubed upper and lower bearings of the motor and the pump. Inspected mechanical seal. Returned to service.	David Wilson	2/1/23	Completed
2/6/23	16969	RAS Pump 1	Monthly Check Pump Couplings	Inspected hub and coupling.	David Wilson	2/1/23	Completed

Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/6/23	16968	RAS Pump 1	RAS Pump #1 PM - Quarterly	LOTO of equipment. Exercised valves. Inspected hubs and coupling. Lubed upper and lower bearings of the motor and the pump. Inspected mechanical seal. Returned to service.	David Wilson	2/1/23	Completed
2/6/23	16945	Grit Screw Drive	Grit Screw Drive Oil Change - Annual		David Wilson	2/1/23	Completed
2/7/23	16790	Generator #2 - Backup Detroit 500	Generator - Monthly Load Test		David Wilson	1/1/23	Completed
2/7/23	16940	Generator #1- Emergency Kohler 750	Generator - Monthly Load Test		David Wilson	2/5/23	Completed
2/7/23	17408	PS 9 Pump 1	Bypass pump set up as backup to pump 1.	DW/LB Yaskawa cooling fans on order. Set up 6" Thompson pump at PS9 as a backup to pump 1.	David Wilson	2/7/23	Completed
2/9/23	17069	All Plant Gear box reducers	GEAR BOX MAINT - WEEKLY		David Wilson	2/5/23	Completed
2/9/23	16944	Grit Screw Classifier	Grit classifier Oil Change - Annual	Locked out classifier (#29). Removed belt guard. Inspected belts and pulleys. Removed drain plug and drained oil. Moved vent plug to 12 o'clock position instead of oil level hole. Inspected classifier shoe hardware.	David Wilson	2/1/23	Completed
2/9/23	16931	Portable Generator - Honda	Portable Generator Inspection - Monthly		David Wilson	2/1/23	Completed
2/14/23	16986	PS 1	PUMP STATIONS - QUATERLY PM'S		David Wilson	2/7/23	Completed
2/14/23	16989	PS 3	PUMP STATIONS - QUATERLY PM'S		David Wilson	2/7/23	Completed
2/14/23	16998	PS A	PUMP STATIONS - QUATERLY PM'S		David Wilson	2/7/23	Completed
2/14/23	17002	PS 1 Generator	PS #1 Generator Inspection and Test - Weekly		David Wilson	2/8/23	Completed
2/14/23	17006	PS 3 Generator	PS #3 Generator Inspection and Test - Weekly		David Wilson	2/8/23	Completed
2/14/23	17012	PS 4 Generator	PS #4 Generator Inspection and Test - Weekly		Eric Sutton	2/8/23	Completed
2/14/23	17026	PS 6 Generator	PS #6 Generator Inspection and Test - Weekly		Eric Sutton	2/8/23	Completed
2/14/23	17016	PS 5 Generator	PS #5 Generator Inspection and Test - Weekly		Eric Sutton	2/8/23	Completed
2/14/23	17022	PS 9 Generator	PS #9 Generator Inspection and Test - Weekly		David Wilson	2/8/23	Completed
2/14/23	17056	High level floats	Weekly High Float Alarm test		Luis Bello	2/5/23	Completed
2/14/23	16950	Mechanical Screen & Washpress System	Monthly Maintenance	Cleaned and inspected wash press and flexrake. Lubed bearings.	David Wilson	2/6/23	Completed
2/14/23	16990	PS 4	PUMP STATIONS - QUATERLY PM'S	Laboa boarrigo.	David Wilson	2/7/23	Completed
2/14/23	16993	PS 5	PUMP STATIONS - QUATERLY PM'S		David Wilson	2/7/23	Completed
2/14/23	16994	PS 6	PUMP STATIONS - QUATERLY PM'S		David Wilson	2/7/23	Completed
2/14/23	16997	PS 9	PUMP STATIONS - QUATERLY PM'S		David Wilson	2/7/23	Completed
2/15/23	17070	All Plant Gear box reducers	GEAR BOX MAINT - WEEKLY		Luis Bello	2/12/23	Completed
2/15/23	17057	High level floats	Weekly High Float Alarm test		Luis Bello	2/12/23	Completed

Flevenia		aintenance					
Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/15/23	16947	Influent Sluice Isolation Gate	Weekly operate through full range		David Wilson	2/8/23	Completed
2/15/23	16962	Aeration Tank 1 Oxygen Probe	AT #1 DO Probe Clean and Calibrate - Monthly	Cleaned and inspected LDO probe. Tested calibration70 ppm offset.	David Wilson	2/7/23	Completed
2/15/23	16963	Aeration Tank 3 Oxygen Probe	AT #3 DO Probe Clean and Calibrate - Monthly	Cleaned and inspected LDO probe. Tested calibration. 1.80ppm offset.	David Wilson	2/7/23	Completed
2/16/23	16889	Chlorine probe ATI	Change electrolyte		Joe Basler	1/1/23	Completed
2/16/23	16887	Chlorine probe ATI	Weekly calibration		Joe Basler	1/16/23	Completed
2/16/23	16888	Chlorine probe ATI	Weekly calibration		David Wilson	1/30/23	Completed
2/16/23	17065	Generators "All Pump Station"	Generator Weekly - Test Run no load		David Wilson	2/13/23	Completed
2/16/23	16941	Generator #1- Emergency Kohler 750	Generator Weekly - Test Run no load		David Wilson	2/13/23	Completed
2/16/23	17038	PS Kholer Trailer Mounted Generator	Generator Weekly - Test Run no load		David Wilson	2/13/23	Completed
2/16/23	16937	Generator #2 - Backup Detroit 500	Generator Weekly - Test Run no load		David Wilson	2/13/23	Completed
2/16/23	16948	Influent Sluice Isolation Gate	Weekly operate through full range		David Wilson	2/15/23	Completed
2/16/23	17003	PS 1 Generator	PS #1 Generator Inspection and Test - Weekly		David Wilson	2/15/23	Completed
2/16/23	17007	PS 3 Generator	PS #3 Generator Inspection and Test - Weekly		David Wilson	2/15/23	Completed
2/16/23	17013	PS 4 Generator	PS #4 Generator Inspection and Test - Weekly		David Wilson	2/15/23	Completed
2/16/23	17027	PS 6 Generator	PS #6 Generator Inspection and Test - Weekly		David Wilson	2/15/23	Completed
2/16/23	17017	PS 5 Generator	PS #5 Generator Inspection and Test - Weekly		David Wilson	2/15/23	Completed
2/16/23	17023	PS 9 Generator	PS #9 Generator Inspection and Test - Weekly		David Wilson	2/15/23	Completed
2/16/23	17063	pH meter	Clean and Calibrate	Cleaned and calibrated pH meter. Offset .43	David Wilson	2/1/23	Completed
2/16/23	17064	ORP meter	Clean and Calibrate	Cleaned and calibrated ORP meter. Offset 1.9mV	David Wilson	2/10/23	Completed
2/16/23	16967	Wet Scrubber Fan	Scrubber Exhaust Fan PM - Monthly	LOTO of equipment. Inspected belt deflection and pulleys. Cleaned and inspected pillow block bearings. Inspected motor seals and bearings. Lubed all bearings and checked mounting hardware.	David Wilson	2/8/23	Completed
2/21/23	16951	Influent Pump 1	Monthly Check Pump Couplings		David Wilson	2/1/23	Completed
2/21/23	16952	Influent Pump 2	Monthly Check Pump Couplings		David Wilson	2/1/23	Completed
2/21/23	16953	Influent Pump 3	Monthly Check Pump Couplings		David Wilson	2/1/23	Completed
2/21/23	16954	Influent Pump 4	Monthly Check Pump Couplings		David Wilson	2/1/23	Completed
2/21/23	16955	Influent Pump 5	Monthly Check Pump Couplings		David Wilson	2/1/23	Completed
2/21/23	16975	RST Feed Pump 1	Monthly Check Pump Couplings		David Wilson	2/1/23	Completed

Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/21/23	16976	RST Feed Pump 2	Monthly Check Pump Couplings		David Wilson	2/1/23	Completed
2/21/23	16982	Sludge Transfer Pump 1	Monthly Check Pump Couplings		David Wilson	2/1/23	Completed
2/21/23	16983	Sludge Transfer Pump 2	Monthly Check Pump Couplings		David Wilson	2/1/23	Completed
2/21/23	16974	RST Feed Pump 1	Vaughan Centrifugal pump - Semi Annual		David Wilson	2/16/23	Completed
2/21/23	16977	RST Feed Pump 2	Vaughan Centrifugal pump - Semi Annual		David Wilson	2/16/23	Completed
2/21/23	16978	Primary Sludge Pump 1	Vaughan Centrifugal pump - Semi Annual		David Wilson	2/16/23	Completed
2/21/23	16981	Primary Sludge Pump 2	Vaughan Centrifugal pump - Semi Annual		David Wilson	2/16/23	Completed
2/22/23	16942	Generator #1- Emergency Kohler 750	Generator Weekly - Test Run no load		David Wilson	2/20/23	Completed
2/22/23	16938	Generator #2 - Backup Detroit 500	Generator Weekly - Test Run no load		David Wilson	2/20/23	Completed
2/22/23	17039	PS Kholer Trailer Mounted Generator	Generator Weekly - Test Run no load		Eric Sutton	2/20/23	Completed
2/22/23	17066	Generators "All Pump Station"	Generator Weekly - Test Run no load		David Wilson	2/20/23	Completed
2/22/23	17004	PS 1 Generator	PS #1 Generator Inspection and Test - Weekly		David Wilson	2/22/23	Completed
2/22/23	17008	PS 3 Generator	PS #3 Generator Inspection and Test - Weekly		David Wilson	2/22/23	Completed
2/22/23	17014	PS 4 Generator	PS #4 Generator Inspection and Test - Weekly		David Wilson	2/22/23	Completed
2/22/23	17018	PS 5 Generator	PS #5 Generator Inspection and Test - Weekly		David Wilson	2/22/23	Completed
2/22/23	17024	PS 9 Generator	PS #9 Generator Inspection and Test - Weekly		David Wilson	2/22/23	Completed
2/22/23	17028	PS 6 Generator	PS #6 Generator Inspection and Test - Weekly		David Wilson	2/22/23	Completed
2/22/23	16949	Influent Sluice Isolation Gate	Weekly operate through full range		David Wilson	2/22/23	Completed
2/22/23	17058	High level floats	Weekly High Float Alarm test		Luis Bello	2/19/23	Completed
2/22/23	17071	All Plant Gear box reducers	GEAR BOX MAINT - WEEKLY		David Wilson	2/19/23	Completed
2/23/23	16985	Waste Activated Sludge Pump 3	Vaughan Centrifugal pump - Semi Annual	Completed service. Oil level good. Inspected hubs and coupling. Greased motor bearings. Exercised valves.	David Wilson	2/16/23	Completed
2/27/23	17061	Recirculation pump #1	Monthly Check Pump Couplings		David Wilson	2/1/23	Completed
2/27/23	16966	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	2/1/23	Completed
2/27/23	17035	GODWIN Portable Pump	Test Run Godwin Pump-Monthly		SEMS TABLET #2	2/1/23	Completed
2/27/23	17060	Meters - 4 Gas Confined Space #2	4 gas meter calibration - monthly		SEMS TABLET #2	2/1/23	Completed
2/27/23	17033	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	2/1/23	Completed
2/27/23	16964	Effluent Pumps	Effluent Pump - Monthly		SEMS TABLET #2	2/15/23	Completed

Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/27/23	17049	GasAlert Max XTII #2	monthly calibration		SEMS TABLET #2	2/23/23	Completed
2/27/23	17041	Ventis MX4 #2 - 4 Gas	4 Gas Meter #2 Calibration - Monthly		SEMS TABLET #2	2/23/23	Completed
2/27/23	17042	Ventis MX4 #3 - 4 Gas	4 Gas Meter #3 Calibration - Monthly		SEMS TABLET #2	2/23/23	Completed
2/27/23	17043	Ventis MX4 #4 - 4 Gas	4 Gas Meter #4 Calibration - Monthly		SEMS TABLET #2	2/23/23	Completed
2/27/23	17044	Ventis MX4 #5 - 4 Gas	4 Gas Meter #5 Calibration - Monthly		SEMS TABLET #2	2/23/23	Completed
2/27/23	17045	Ventis MX4 #6 - 4 Gas	4 Gas Meter #6 Calibration - Monthly		SEMS TABLET #2	2/23/23	Completed
2/27/23	16917	ATI Wet Hydrogen Sulfide Monitor Exhaust	System Maintenance		SEMS TABLET #2	1/1/23	Completed
2/27/23	16911	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	1/1/23	Completed
2/27/23	16818	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	1/1/23	Completed
2/27/23	16912	PS Onan Trailer mounted generator	Quarterly Loaded test run		SEMS TABLET #2	1/1/23	Completed
2/27/23	16869	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	1/1/23	Completed
2/27/23	16898	Recirculation pump #1	Monthly Check Pump Couplings			1/4/23	Completed
2/27/23	16716	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	12/1/22	Completed
2/27/23	16756	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	12/1/22	Completed
2/27/23	16662	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	12/1/22	Completed
2/27/23	16744	Recirculation pump #1	Monthly Check Pump Couplings			12/7/22	Completed
2/27/23	16558	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	11/1/22	Completed
2/27/23	16491	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	11/1/22	Completed
2/27/23	16591	Recirculation pump #1	Monthly Check Pump Couplings			11/2/22	Completed
2/27/23	16603	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	11/1/22	Completed
2/27/23	16571	Ventis MX4 #5 - 4 Gas	4 Gas Meter #5 Calibration - Monthly		SEMS TABLET #2	11/24/22	Completed
2/27/23	16370	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	10/1/22	Completed
2/27/23	16421	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	10/1/22	Completed
2/27/23	16319	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	10/1/22	Completed
2/27/23	16422	PS Onan Trailer mounted generator	Quarterly Loaded test run		SEMS TABLET #2	10/1/22	Completed
2/27/23	16406	Recirculation pump #1	Monthly Check Pump Couplings			10/5/22	Completed
2/27/23	16382	Ventis MX4 #5 - 4 Gas	4 Gas Meter #5 Calibration - Monthly		SEMS TABLET #2	10/27/22	Completed

Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/27/23	16211	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	9/1/22	Completed
2/27/23	16250	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	9/1/22	Completed
2/27/23	16157	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	9/1/22	Completed
2/27/23	16238	Recirculation pump #1	Monthly Check Pump Couplings			9/7/22	Completed
2/27/23	16072	pH meter	Clean and Calibrate		SEMS TABLET #2	8/1/22	Completed
2/27/23	16041	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	8/1/22	Completed
2/27/23	16084	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	8/1/22	Completed
2/27/23	15969	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	8/1/22	Completed
2/27/23	16070	Recirculation pump #1	Monthly Check Pump Couplings			8/3/22	Completed
2/27/23	15871	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	7/1/22	Completed
2/27/23	15911	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	7/1/22	Completed
2/27/23	15912	PS Onan Trailer mounted generator	Quarterly Loaded test run		SEMS TABLET #2	7/1/22	Completed
2/27/23	15820	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	7/1/22	Completed
2/27/23	15898	Recirculation pump #1	Monthly Check Pump Couplings			7/6/22	Completed
2/27/23	15715	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	6/1/22	Completed
2/27/23	15755	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	6/1/22	Completed
2/27/23	15655	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	6/1/22	Completed
2/27/23	15743	Recirculation pump #1	Monthly Check Pump Couplings			6/1/22	Completed
2/27/23	15550	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	5/1/22	Completed
2/27/23	15595	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	5/1/22	Completed
2/27/23	15489	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	5/1/22	Completed
2/27/23	15582	Recirculation pump #1	Monthly Check Pump Couplings			5/4/22	Completed
2/27/23	15389	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	4/1/22	Completed
2/27/23	15434	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	4/1/22	Completed
2/27/23	15435	PS Onan Trailer mounted generator	Quarterly Loaded test run		SEMS TABLET #2	4/1/22	Completed
2/27/23	15336	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	4/1/22	Completed

Status	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
Date 2/27/23	15421	Recirculation pump #1	Monthly Check Pump Couplings			4/6/22	Completed
2/27/23	15238	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	3/1/22	Completed
2/27/23	15277	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	3/1/22	Completed
2/27/23	15178	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	3/1/22	Completed
2/27/23	15264	Recirculation pump #1	Monthly Check Pump Couplings			3/2/22	Completed
2/27/23	15068	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	2/1/22	Completed
2/27/23	15095	Recirculation pump #1	Monthly Check Pump Couplings			2/2/22	Completed
2/27/23	15001	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	2/1/22	Completed
2/27/23	15107	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	2/1/22	Completed
2/27/23	14836	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	1/1/22	Completed
2/27/23	14887	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	1/1/22	Completed
2/27/23	14930	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	1/1/22	Completed
2/27/23	14931	PS Onan Trailer mounted generator	Quarterly Loaded test run		SEMS TABLET #2	1/1/22	Completed
2/27/23	14898	Ventis MX4 #5 - 4 Gas	4 Gas Meter #5 Calibration - Monthly		SEMS TABLET #2	1/27/22	Completed
2/27/23	14916	Recirculation pump #1	Monthly Check Pump Couplings			1/5/22	Completed
2/27/23	14727	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	12/1/21	Completed
2/27/23	14766	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	12/1/21	Completed
2/27/23	14667	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	12/1/21	Completed
2/27/23	14754	Recirculation pump #1	Monthly Check Pump Couplings			12/1/21	Completed
2/27/23	14754	Recirculation pump #1	Monthly Check Pump Couplings			12/1/21	Completed
2/27/23	14570	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	11/1/21	Completed
2/27/23	14616	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	11/1/21	Completed
2/27/23	14509	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	11/1/21	Completed
2/27/23	14404	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	10/1/21	Completed
2/27/23	14603	Recirculation pump #1	Monthly Check Pump Couplings			11/3/21	Completed
2/27/23	14353	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	10/1/21	Completed
2/27/23	14448	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	10/1/21	Completed

Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/27/23	14449	PS Onan Trailer mounted generator	Quarterly Loaded test run		SEMS TABLET #2	10/1/21	Completed
2/27/23	14434	Recirculation pump #1	Monthly Check Pump Couplings			10/6/21	Completed
2/27/23	14238	PS 4 Generator	PS #4 Generator Inspection and Load Test - Monthly		SEMS TABLET #2	9/1/21	Completed
2/27/23	14265	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	9/1/21	Completed
2/27/23	14291	Recirculation pump #1	Monthly Check Pump Couplings			9/1/21	Completed
2/27/23	14303	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	9/1/21	Completed
2/27/23	14205	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	9/1/21	Completed
2/27/23	14035	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	8/1/21	Completed
2/27/23	14101	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	8/1/21	Completed
2/27/23	14144	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	8/1/21	Completed
2/27/23	13918	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	7/1/21	Completed
2/27/23	14130	Recirculation pump #1	Monthly Check Pump Couplings			8/4/21	Completed
2/27/23	13867	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	7/1/21	Completed
2/27/23	13956	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	7/1/21	Completed
2/27/23	13957	PS Onan Trailer mounted generator	Quarterly Loaded test run		SEMS TABLET #2	7/1/21	Completed
2/27/23	13944	Recirculation pump #1	Monthly Check Pump Couplings			7/7/21	Completed
2/27/23	13794	Recirculation pump #1	Monthly Check Pump Couplings			6/2/21	Completed
2/27/23	13766	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	6/1/21	Completed
2/27/23	13804	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	6/1/21	Completed
2/27/23	13814	Wet Scrubber System	Clean and Calibration		SEMS TABLET #2	6/1/21	Completed
2/27/23	13658	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	5/1/21	Completed
2/27/23	13614	Ventis MX4 #4 - 4 Gas	4 Gas Meter #4 Calibration - Monthly		SEMS TABLET #2	5/27/21	Completed
2/27/23	13637	Recirculation pump #1	Monthly Check Pump Couplings			5/5/21	Completed
2/27/23	13657	PS D - DPW Stormwater Pump Station	Generator Monthly test run		SEMS TABLET #2	4/1/21	Completed
2/27/23	13077	Sludge Storage Tank 2	Sludge Holding Tank #2 Cleaning - Annual		SEMS TABLET #2	2/3/21	Completed
2/28/23	17072	All Plant Gear box reducers	GEAR BOX MAINT - WEEKLY		SEMS TABLET #2	2/26/23	Completed
2/28/23	17059	High level floats	Weekly High Float Alarm test		SEMS TABLET #2	2/26/23	Completed

Status Date	WO #	Asset Name	Work Description	Work History Note	Employee	Schedule Date	Status
2/28/23	17073	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	2/1/23	Completed
2/28/23	17073	PS Onan Trailer mounted generator	Montly operational test run		SEMS TABLET #2	2/1/23	Completed
2/28/23	16943	Generator #1- Emergency Kohler 750	Generator Weekly - Test Run no load		SEMS TABLET #2	2/27/23	Completed
2/28/23	16939	Generator #2 - Backup Detroit 500	Generator Weekly - Test Run no load		SEMS TABLET #2	2/27/23	Completed
2/28/23	17067	Generators "All Pump Station"	Generator Weekly - Test Run no load		SEMS TABLET #2	2/27/23	Completed
2/28/23	17040	PS Kholer Trailer Mounted Generator	Generator Weekly - Test Run no load		SEMS TABLET #2	2/27/23	Completed

Date	Asset ID	Asset Description	Asset Class
2/16/2023 9:11	04-018	11 WESTERN AVE	Hull Parcels
2/16/2023 9:07	06-055	127 SPRING ST	Hull Parcels
2/28/2023 7:48	09-044-A	3 FITZPATRICK WAY	Hull Parcels
2/7/2023 14:22	10 Nantasket Ave	10 Nantasket Ave Grinder Pump	Hull Grinder Pumps
2/5/2023 12:18	101 Rockaway Ave	101 Rockaway Ave Grinder Pump	Hull Grinder Pumps
2/10/2023 8:19	101 Rockaway Ave	101 Rockaway Ave Grinder Pump	Hull Grinder Pumps
2/10/2023 8:21	101 Rockaway Ave	101 Rockaway Ave Grinder Pump	Hull Grinder Pumps
2/13/2023 9:30	11-011	895 NANTASKET AVE	Hull Parcels
2/10/2023 7:55	11-060	5 BEACON RD	Hull Parcels
2/27/2023 14:36	12-069	10 BLUFF RD	Hull Parcels
2/10/2023 7:50	12-081	836 NANTASKET AVE	Hull Parcels
2/17/2023 9:54	13-065	804 NANTASKET AVE	Hull Parcels
2/5/2023 12:12	145 N Truro St	145 N Truro St Grinder Pump	Hull Grinder Pumps
2/5/2023 12:15	145 N Truro St	145 N Truro St Grinder Pump	Hull Grinder Pumps
2/23/2023 10:21	15-008	729 NANTASKET AVE	Hull Parcels
2/16/2023 9:26	15-029	743 NANTASKET AVE	Hull Parcels
2/16/2023 9:28	15-047	46 L STREET	Hull Parcels
2/23/2023 10:28	15-161	48 O STREET	Hull Parcels
2/23/2023 10:31	15-196	40 P STREET	Hull Parcels
2/16/2023 9:37	16-079	5 E STREET	Hull Parcels
2/16/2023 9:39	16-081	9 E STREET	Hull Parcels
2/16/2023 9:42	16-087	21 E STREET	Hull Parcels
2/16/2023 9:46	17-118-A	57 E STREET	Hull Parcels
2/16/2023 9:48	17-119	59 E STREET	Hull Parcels
2/16/2023 10:00	17-126	77 E STREET	Hull Parcels
2/17/2023 12:35	19-043	70 A STREET	Hull Parcels
2/17/2023 12:32	19-045	168 MANOMET AVE	Hull Parcels
2/24/2023 13:20	19-147	176 SAMOSET AVE	Hull Parcels
2/17/2023 12:28	21-011	162 SAMOSET AVE	Hull Parcels
2/15/2023 9:35	21-055	118 MANOMET AVE	Hull Parcels
2/15/2023 9:38	21-059	110 MANOMET AVE	Hull Parcels
2/15/2023 9:50	21-063	102 MANOMET AVE	Hull Parcels
2/21/2023 13:59	22-142	259 KINGSLEY RD	Hull Parcels
2/23/2023 10:14	22-170	91 TOURAINE AVE	Hull Parcels
2/17/2023 12:24	23-086	6 WARREN STREET	Hull Parcels
2/15/2023 9:46	23-130	24 WARREN STREET	Hull Parcels
2/15/2023 9:55	23-135	90 MANOMET AVE	Hull Parcels
2/15/2023 10:05	23-139	82 MANOMET AVE	Hull Parcels
2/15/2023 10:11	23-154	147 KENBERMA ST	Hull Parcels
2/10/2023 7:59		25 WARFIELD AVE	Hull Parcels
2/23/2023 10:05		25 WARFIELD AVE	Hull Parcels
2/16/2023 10:26		81 WARFIELD AVE	Hull Parcels
2/15/2023 9:23	25-015	64 MANOMET AVE	Hull Parcels

2/15/2023 9:16 25-020 2/17/2023 12:16 25-042 2/17/2023 12:21 25-055 2/15/2023 9:08 25-088 2/15/2023 8:54 25-089 2/17/2023 12:13 25-090 2/21/2023 14:02 25-090 2/15/2023 8:27 25-095 2/15/2023 8:21 25-096 2/15/2023 8:10 25-166 2/15/2023 8:04 27-006 2/10/2023 8:01 27-015 2/17/2023 12:08 27-018 2/16/2023 10:35 28-051 2/16/2023 11:19 29-138 2/1/2023 12:55 30-042 2/27/2023 10:18 30-042 2/1/2023 12:57 31-063 2/27/2023 10:20 31-063 2/4/2023 15:38 32 Richards Rd 2/16/2023 11:23 32-072 2/10/2023 8:05 34 Wyola Rd 2/10/2023 8:17 34 Wyola Rd 2/1/2023 12:53 35-031 2/27/2023 9:53 35-031 2/1/2023 12:51 35-032 2/1/2023 12:49 36-006 2/27/2023 9:51 36-006 2/17/2023 11:59 36-012 2/17/2023 12:00 36-013 2/16/2023 11:33 36-080 2/16/2023 11:39 36-164 2/6/2023 10:28 49-065 2/10/2023 8:22 51-115 2/21/2023 14:10 52-021 2/21/2023 14:07 52-066 2/21/2023 14:11 53-046 2/24/2023 7:24 54 Salisbury St 2/16/2023 11:41 54-022 2/7/2023 14:23 Bacteria UNIT #21 2/16/2023 14:33 Bacteria UNIT #21 2/16/2023 14:37 Bacteria UNIT #22 2/16/2023 14:27 Bateria UNIT # 8 2/16/2023 13:59 Bateria UNIT #1

52 MANOMET AVE 74 SAMOSET AVE **42 MASSASOIT AVE 98 REVERE ST** 44 MANOMET AVE **42 MANOMET AVE 42 MANOMET AVE** 34 MANOMET AVE 32 MANOMET AVE **26 MANOMET AVE 14 MANOMET AVE 13 MANOMET AVE 19 MANOMET AVE 31 WALTHAM ST** 51 MOUNTFORD RD **1 NINTH STREET 1 NINTH STREET 145 EDGEWATER RD 145 EDGEWATER RD** 32 Richards Rd Grinder Pump 44 CLIFTON AVE 34 Wyola Rd Grinder Pump 34 Wyola Rd Grinder Pump **109 BAY STREET 109 BAY STREET 19 ISLAND VIEW RD 48 BAY STREET 48 BAY STREET 33 BAY STREET 35 BAY STREET** 3 STANDISH RD **51 HAMPTON CIRCLE 5 STATE PARK RD 12 SEA VIEW AVE 150 ATLANTIC AVE** 14 GUN ROCK AVE **104 ATLANTIC AVE** 54 Salisbury St Grinder Pump 20 SUMMIT AVE UNIT #21 UNIT #21 UNIT #22 UNIT #8 UNIT #1

Hull Parcels Hull Grinder Pumps Hull Parcels **Hull Grinder Pumps** Hull Grinder Pumps Hull Parcels **Hull Grinder Pumps** Hull Parcels Hull In Pipe Bacteria Unit Hull In Pipe Bacteria Unit

2/16/2023 14:28 Bateria UNIT #10 **UNIT #10** 2/16/2023 14:31 Bateria UNIT #11 UNIT #11 2/16/2023 14:36 Bateria UNIT #12 **UNIT #12** 2/16/2023 14:35 Bateria UNIT #13 UNIT #13 2/16/2023 14:34 Bateria UNIT #14 **UNIT #14** 2/16/2023 14:33 Bateria UNIT #15 UNIT #15 2/16/2023 14:32 Bateria UNIT #16 **UNIT #16** 2/16/2023 14:28 Bateria UNIT #17 UNIT #17 2/16/2023 14:29 Bateria UNIT #19 **UNIT #19** 2/16/2023 13:59 Bateria UNIT #2 UNIT #2 2/16/2023 14:32 Bateria UNIT #20 **UNIT #20** 2/16/2023 14:36 Bateria UNIT #23 **UNIT #23** 2/16/2023 13:57 Bateria UNIT #24 **UNIT #24** 2/7/2023 14:25 Bateria UNIT #3 UNIT #3 2/16/2023 14:29 Bateria UNIT #3 UNIT #3 2/7/2023 14:26 Bateria UNIT #4 UNIT #4 2/16/2023 13:57 Bateria UNIT #4 UNIT #4 2/16/2023 14:24 Bateria UNIT #5 UNIT #5 2/16/2023 14:01 Bateria UNIT #6 UNIT #6 2/16/2023 14:27 Bateria UNIT #7 UNIT #7 2/16/2023 14:37 Bateria UNIT #9 **UNIT #9** 2/16/2023 13:39 HULL_MH-25101 MH-25101 2/9/2023 8:49 MH-20012 SEMS Asset SEMS Asset 2/21/2023 14:17 MH-20037 2/9/2023 8:44 MH-20141 SEMS_Asset 2/9/2023 8:41 MH-20143 SEMS Asset 2/9/2023 8:38 MH-20221 SEMS Asset 2/20/2023 11:59 MH-20299 SEMS_Asset 2/9/2023 8:35 MH-20390 SEMS Asset SEMS_Asset 2/16/2023 13:45 MH-20580 2/16/2023 13:42 MH-20664 SEMS Asset 2/21/2023 14:04 MH-20693 SEMS Asset 2/16/2023 13:41 MH-20803 SEMS_Asset 2/6/2023 14:42 MH-20818 SEMS Asset 2/6/2023 14:43 MH-20824 SEMS Asset 2/6/2023 14:50 MH-20829 SEMS_Asset 2/6/2023 14:53 MH-20830 SEMS Asset 2/6/2023 14:51 MH-20831 SEMS Asset 2/22/2023 8:43 MH-20973 SEMS_Asset 2/16/2023 13:52 MH-21026 SEMS Asset 2/9/2023 8:29 MH-30016 SEMS_Asset 2/9/2023 8:31 MH-30017 SEMS Asset 2/16/2023 13:48 MH-30017 SEMS Asset 2/6/2023 14:45 MH-30057 SEMS_Asset Hull In Pipe Bacteria Unit Sanitary Manhole Sanitary Manhole

2/9/2023 8:21 MH-30069	SEMS_Asset	Sanitary Manhole
2/9/2023 8:26 MH-30070	SEMS_Asset	Sanitary Manhole
2/16/2023 13:49 MH-30070	SEMS_Asset	Sanitary Manhole
2/9/2023 8:47 MH-30075	SEMS_Asset	Sanitary Manhole

Sutton, EricHull - MarkoutViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - Sewer BackupViewSutton, EricHull - MarkoutViewSutton, EricHull	Name	Workflow Class	View
Sutton, EricHull - MarkoutViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricSticker Replacement - Grinder PanelsViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView <t< td=""><td>Sutton, Eric</td><td>Hull - Markout</td><td>View</td></t<>	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - Grinder Pump MaintenanceViewSutton, EricSticker Replacement - Grinder PanelsViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - MarkoutViewSutton, EricSticker Replacement - Grinder PanelsViewSutton, EricHull - MarkoutViewSutton, EricHull - Markout <td>Sutton, Eric</td> <td>Hull - Markout</td> <td>View</td>	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - Grinder Pump MaintenanceViewSutton, EricSticker Replacement - Grinder PanelaViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - MarkoutViewSutton, EricHull - Sewer BackupViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricSticker Replacement - Grinder PanelaViewSutton, EricHull - MarkoutViewSutton, EricHull - Marko	Sutton, Eric	Hull - Markout	View
Sutton, EricSticker Replacement - Grinder PanelesViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - Sewer BackupViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - MarkoutViewSutton, EricHull - Markout </td <td>Sutton, Eric</td> <td>Hull - Grinder Pump Maintenance</td> <td>View</td>	Sutton, Eric	Hull - Grinder Pump Maintenance	View
Sutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - Sewer BackupViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView <t< td=""><td>Sutton, Eric</td><td>Hull - Grinder Pump Maintenance</td><td>View</td></t<>	Sutton, Eric	Hull - Grinder Pump Maintenance	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - MarkoutViewSutton, Eric <td>Sutton, Eric</td> <td>Sticker Replacement - Grinder Panels</td> <td>View</td>	Sutton, Eric	Sticker Replacement - Grinder Panels	View
Sutton, EricHull - Sewer BackupViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricSticker Replacement - Grinder PanelsViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton	Sutton, Eric	Hull - Grinder Pump Maintenance	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricSticker Replacement - Grinder PanelsViewSutton, EricHull - MarkoutViewSutton, EricHull -	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - MarkoutViewSutton, EricHull - Marko	Sutton, Eric	Hull - Sewer Backup	View
Sutton, EricHull - MarkoutViewSutton, EricSticker Replacement - Grinder PanelsViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - MarkoutViewSutton, Eri	Sutton, Eric	Hull - Markout	View
Sutton, EricSticker Replacement - Grinder PanelsViewSutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - MarkoutViewSutton, Eri	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - Grinder Pump MaintenanceViewSutton, EricHull - MarkoutViewSutton, EricHull - Marko	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView </td <td>Sutton, Eric</td> <td>Sticker Replacement - Grinder Panels</td> <td>View</td>	Sutton, Eric	Sticker Replacement - Grinder Panels	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView </td <td>Sutton, Eric</td> <td>Hull - Grinder Pump Maintenance</td> <td>View</td>	Sutton, Eric	Hull - Grinder Pump Maintenance	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView </td <td>Sutton, Eric</td> <td>Hull - Markout</td> <td>View</td>	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView </td <td>Sutton, Eric</td> <td>Hull - Markout</td> <td>View</td>	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView </td <td>Sutton, Eric</td> <td>Hull - Markout</td> <td>View</td>	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView </td <td>Sutton, Eric</td> <td>Hull - Markout</td> <td>View</td>	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView </td <td>Sutton, Eric</td> <td>Hull - Markout</td> <td>View</td>	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView </td <td>Sutton, Eric</td> <td>Hull - Markout</td> <td>View</td>	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - Sewer BackupViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutV	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - Sewer BackupViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutV	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - Sewer BackupViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutV	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - Sewer BackupViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutV	Sutton, Eric	Hull - Markout	<u>View</u>
Sutton, EricHull - MarkoutViewSutton, EricHull - Sewer BackupViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutV	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - Sewer BackupViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView	Sutton, Eric	Hull - Markout	<u>View</u>
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView	Sutton, Eric	Hull - Sewer Backup	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutViewSutton, EricHull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, Eric Hull - MarkoutViewSutton, Eric Hull - MarkoutViewSutton, Eric Hull - MarkoutViewSutton, Eric Hull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, Eric Hull - MarkoutViewSutton, Eric Hull - MarkoutViewSutton, Eric Hull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, Eric Hull - MarkoutViewSutton, Eric Hull - MarkoutView	Sutton, Eric	Hull - Markout	View
Sutton, Eric Hull - Markout	Sutton, Eric	Hull - Markout	View
	Sutton, Eric	Hull - Markout	View
Sutton, Eric Hull - Markout View	Sutton, Eric	Hull - Markout	<u>View</u>
	Sutton, Eric	Hull - Markout	View

•	Hull - Markout	<u>View</u>
	Hull - Markout	<u>View</u>
	Hull - Markout	<u>View</u>
-	Hull - Markout	<u>View</u>
-	Hull - Markout	<u>View</u>
Sutton, Eric	Hull - Markout	View
Sutton, Eric	Hull - Markout	View
Sutton, Eric	Hull - Markout	View
Sutton, Eric	Hull - Markout	View
Sutton, Eric	Hull - Markout	View
Sutton, Eric	Hull - Markout	View
Sutton, Eric	Hull - Markout	<u>View</u>
Sutton, Eric	Hull - Markout	<u>View</u>
Sutton, Eric	Hull - Markout	<u>View</u>
Sutton, Eric	Hull - Markout	View
Sutton, Eric	Hull - Markout	View
Sutton, Eric	Hull - Markout	View
Sutton, Eric	Hull - Markout	View
Sutton, Eric	Hull - Markout	View
Basler, Joe	Hull - Grinder Pump Maintenance	View
Sutton, Eric	Hull - Markout	View
	Sticker Replacement - Grinder Panels	View
	Hull - Grinder Pump Maintenance	View
Sutton, Eric	Hull - Markout	View
-	Hull - Markout	View
Sutton, Eric	Hull - Markout	View
-	Hull - Markout	View
-	Hull - Markout	View
	Hull - Markout	View
-	Hull - Markout	View
-	Hull - Markout	View
,	Hull - Markout	View
	Hull - Markout	View
-	Hull - Markout	View
-	Hull - Markout	View
Sutton, Eric	Hull - Markout	View
	Hull - Markout	View
Sutton, Eric	Hull - Grinder Pump Maintenance	View
Sutton, Eric	Hull - Markout	View
Sutton, Eric	Hull - In Pipe Bacteria Units	View
Sutton, Eric	Hull - In Pipe Bacteria Units	View
-	Hull - In Pipe Bacteria Units	View
Sutton, Eric	Hull - In Pipe Bacteria Units	
-	•	<u>View</u>
Sutton, EIIC	Hull - In Pipe Bacteria Units	View

Sutton, Eric Hull - In Pipe Bacteria Units Sutton, Eric Sewer Main Cleaning & CCTV Sutton, Eric Sewer Main Cleaning & CCTV Sutton, Eric MH Frame & Cover Inspection Sutton, Eric Sewer Main Cleaning & CCTV Sutton, Eric Sewer Main Cleaning & CCTV Sutton, Eric Sewer Main Cleaning & CCTV Sutton, Eric MH Frame & Cover Inspection Sutton, Eric Sewer Main Cleaning & CCTV Sutton, Eric Sewer Main Cleaning & CCTV Sutton, Eric Sewer Main Cleaning & CCTV Sutton, Eric MH Frame & Cover Inspection Sutton, Eric Sewer Main Cleaning & CCTV Sutton, Eric MH Frame & Cover Inspection Sutton, Eric Sewer Main Cleaning & CCTV Sutton, Eric Sewer Main Cleaning & CCTV

View

Sutton, Eric	Sewer Main Cleaning & CCTV	View
Sutton, Eric	Sewer Main Cleaning & CCTV	View
Sutton, Eric	Sewer Main Cleaning & CCTV	View
Sutton, Eric	Sewer Main Cleaning & CCTV	View

	Asset Management Accounts - Year 8									e Status
	FOR M.O.R. FEBRUARY 2023		Actual to date		Proj	ected for Final Estin	nate	Budget	NOW=	3/14/2023
Account		Budgeted Amount	<u> </u>		Projected costs and incl PO's	Final est	Delta	expended	Start	5/1/2020
08M-101A	Preventive Maint	\$227,514.68	\$89,071.93	\$138,442.75	\$27,100.00	\$116,171.93	\$111,342.75	39.1%	287.0%	247.9%
08M-102B	Capital and Major Repairs	\$140,000.00	\$167,849.80	(\$27,849.80)	\$54,237.00	\$222,086.80	(\$82,086.80)	119.9%	287.0%	167.1%
08M-103A	Major Sub Contractors	\$192,737.48	\$179,221.42	\$13,516.06	\$44,000.00	\$223,221.42	(\$30,483.94)	93.0%	287.0%	194.0%
blank										
	Asset Management	\$560,252.16	\$436,143.15	\$124,109.01	\$125,337.00	\$561,480.15	(\$1,227.99)	77.8%	287.0%	209.2%
					\$124,109.01			-		-

08S	D Street	\$7,500.00	\$8,391.00	(\$891.00)	\$0.00	\$8,391.00	(\$891.00)	111.9%	287.0%	175.1%
000		<u> </u>	6424 700 00	(\$31,788.00)	\$0.00	\$131,788.00	(\$31.788.00)	121.00/	287.0%	155.29/
08C	Odor Control Chemicals	\$100,000.00	\$131,788.00	(331,788.00)	Ş0.00	\$151,788.00	(351,788.00)	131.8%	287.0%	155.2%

Estin	nated total	
rema	ining 08M,	
	08C	(\$33,015.99)

			Hull 20	022-2023 -	08M Projects, Tasks, and No	eeds - (AV)	
Maintenance Account - Year 8 - 05_01_22 to 04_30_23							
Detection	FOR January 2023 M.O.R.		1		\$125,337.00		
Priority [1=high]	Description	Status	completed	Task	Estimates & funds Final Completed remaining Cost	Lead	
1	Mechanical Work Labor by O&M specialists	On Going		101A	\$10,000.00		Placeholder for Jody St. (8/30; adjust budget 9/20./
1	Pump and Motor Repairs/Replacements [invoiced and pcard]	On Going		101A			to keep existing equipmer purchases. orig budget \$ ZERO [PS4 rebuilt assy]
1	Lubricants	On Going		101A			Various Suppliers for oil a zero 1/3/23
1	Generator Prev. Maintenance and Repairs	On Going		101A	\$10,000.00		Orig budget \$20,000. Ger issued; reduce by minor F to \$10,000 [12/19].
1	Fire Alarm Inspections and Service	On Going		101A			Semi Annual - Hart Secur annual services complete ZERO.
2	Universal waste disposal	completed		101A			Placeholder - \$500 - Unlik disposal. Completed Dec
1	Service the Forklift	completed		101A	\$231.00		Placeholder \$400 - Annua
1	Overhead Hoist Inspection & repairs	completed		101A	\$1,666.52		Annual task - Applied Dyr actions, \$1500 left to do f
1	Flow meter verification and calibration	completed		101A	\$1,175.00		Placeholder - Annual - Ra to be contacted. Early No
1	Facility Building - Roof Inspection	completed		101A	\$2,800.00		\$2800 Annual Placeholde
2	Jerome H2S Meter Inspection	Pending		101A	\$1,100.00		Placeholder if meter is se needed and if new meter
1	Janitorial Supplies	On Going		101A			Orig budget \$3,000 - Esti 1/3/23
1	Manhole Inspections	Pending		101A			As required,and/or sched
2	General mechanical and electrical items/supplies	On Going		101A			Grainger, FWWebb, EJP, progresses; adj 8/30; adju
1	Thompson Pump repairs 6TS-244 [6A]	completed		101A			Rotating assembly failure repair. All bills to post by e
2	Large Hoses & fittings	On Going		101A			Orig budget \$3,000. Rep NIR and Wolf Creek. ZEF
1	hypo room access/entry door	Pending		102B	\$10,737.00		D&C Quoted - waiting for confirmed with email to D
3	Misc. Materials	on Going		101A			Hardware Store - \$200.00 9/20; adj 11/28. Adjust t
	New Hach Spec Meter for chlorine	completed		101A			replace older/failing unit [I
1	Lab Equip Calibration	completed		101A			Annual service \$640

3/14/2023 14:11

Comments

t. George, Paul Horigan & WC Support Staff - Total budget \$25,000; adjust D.Adjust budget 11/28; adjust budget 12/19 by 2K.

ent running - utilize various outside contractor repair shops, new (\$20,000; adj 8/30; adj 9/26; adj 11/28 to \$9,000; Reduce budget to *y*]

il and grease. Budgeted \$2000. Cut placeholder \$\$ to \$900; Adjust to

eneral PM and CM Repair Work - **Placeholder** - New PO needs to be r PM costs/invoices paid 11/28 - reduce by \$3,500. Adj placeholder down

urity [October & April, central station, & Service]budget \$3000. Semited in mid April. Adj 8/30; Oct Service completed. Adjust budget down to

likely to be used in year 8. Will use these funds for electronic waste ec 2023

nual cost - outside vendor. Completed June 2022

ynamics - Inspection Work - May 2022 \$1500 plus some corrective o for repairs [completed Aug 2022];

Ray Ferland or other 1 visit annually - Targeting June 2022. Vendor needs Nov targeted date. Nov. Service completed.

der - Established contract with Tecta America. Completed May 2022

sent out for calibration - \$1,100; Update Sept 2022 - meter evaluation er should be considered.

stimated annual expenditures - adjust 8/30; Adjust 10/31. Adjust to zero

eduled

P,Hoadley, mcMasterCarr, etc; orig budget \$20,000, adjust tdown as year djust in Sept to 5,000. Adjust 11/28 to \$3,000; Adjust t zero on 1/3/23

re - bearings, shft, mech seal parts & labor. Est labor \$6500. Seacoast y end of September

eplacements and/or Service - On-Going - As Needed; adj budget Sept. ERO out the budget 12/19/22

or updated quote with FRP door - Estimate \$6,500; updated estimate, D&C & HSD approval.

00 per month - reoccurring expense; budget \$2,400; Adjust 8/30; Adj t to zero 1/3/23

t [DR700]; new unit purchased May 2022

	Hull 2022-2023 - 08M Projects, Tasks, and Needs - (AV) Maintenance Account - Year 8 - 05_01_22 to 04_30_23							
	FOR January 2023 M.O.R.				\$125,337.00			
Priority [1=high]	Description	Status	completed	Task	Estimates & funds remaining	Final Completed Cost	Lead	
1	RAS pumps - spare impeller	On Going		101A	\$3,000.00			4-6 week lead time ARO. 2022 piece is being made
	Duperon Service Call	completed		101A		\$2,500.00		Service done - Septembe
2	6" plug valves [4]	completed		101A		\$3,713.40		RAS pump #3 discharge & 2022. GT1 outlet valve re access.
1	Duperon Service Call - Additional needs	completed		102B				Issued PO 105426 - \$8,20
2	New Magnetic flow meters for RAS and WAS	Pending		102B				hardware - does not inclu Remove from planned pro
2	yard hydrants - installation	completed		102B				sub-contractor labor - per Completed Dec 2022 inclu
1	Mech seals for new PS4 pumps & barrier tanks	completed		102B		\$10,068.55		Items ordered after appro
1	Pump Station #4 -New Pumps install	completed		102B		\$12,237.61		by D & C. Late June 202
1	Effluent Pump #3 - repairs	completed		102B		\$26,840.20		pump has been returned
3	Sanitaire hardware purchase for aer tk 1	Pending		102B				Purchase more hardware
1	D&C plant water and potable water system repairs, upgrades various. Replace 6" potable water valve in basement and misc. valves	completed		102B		\$43,499.70		Also check/replace 1 1/4 etc. T&M. Estimate \$43,0
2	new effluent P1 - Flowserve	completed		102B				Update 2/8 to AquaSolu delivered in late Septem
2	Pump Station #3 - spare rotating, assy, or pump	Pending		102B				TBD- estimates being obt
3	New 4-inch valves for pri building between the tanks Installation	Pending		102B				Valves - cost: \$3000, sub
3	Odor log data loggers & calibr kit	Pending		102B				Current units obsolete and remove the \$6,000 on 2/6
3	Jerome meter replacement	Pending		102B				replace unit, if done \$11,0
3	Gravity Thickener #1 sandblasting/painting	Pending		102B				Estimate \$50,000+ - woul
2	Duperon Sumitomo Gear boxes	completed		102B		\$8,500.00		one spare gear box for fle in late August 2022. Wait

3/14/2023 14:11

Comments

D. Ordered July 2022; Waiting for updated delivery date. Confirmed Nov de.

ber 2022. Recommendations made.

e & other. Pratt plug valves -Qty 4. ordered May 2022; received Aug repaired and install flush connection. Difficult to remove due to limited

,269; work completed late Nov 2022.

slude installation [estimate for Equip - \$8,500] May or may not occur. projects for 08M.

ending; Have materials on hand. Spring 2022. Targeting Nov 2022. Including conduit trench from Sec building to CCT.

roval. Installed & in service Aug 2022.

022 - revised estimated installation cost. Work completed July 2022.

d to facility

re ??

4 valves as needed - Requires a water shutdown, other drainage piping, 3,000

lutions - purchase of new spare effluent pump #1 - 60HP pump ember. Cost encumbered in 07M. Pump received and paid for 07M.

btained

sub-contracted labor - either WC or outside co.\$5,000 - totl estim \$8,000

and not supported by company, possibly look at under 05C if funds avail; 2/6/20 - 06C or 06M

1,000; evaluating options

ould need to go out for competitive bid request

flex rake and wash compactor [Delte Elec] ordered June 2022. Received aiting for invoicing. On Purchase order.

			Hull 20)22-2023 -	08M Projects,	Tasks, and Ne	eds - (AV)	
			Maint	enance Ac	count - Year 8	- 05_01_22 to	04_30_23	
	FOR January 2023 M.O.R.		1		\$125,337.00			
Priority [1=high]	Description	Status	completed	Task	Estimates & funds remaining	Final Completed Cost	Lead	
1	Grit classifier system parts	On Going		102B	\$3,500.00			waiting for wear shoes - 2022. Plan for additiona by various vendors incl
	Plant Water System [Pump and/or parts]	On Going		102B				consider spare motor or co
1	Replacement Pumps LS A [see notes]	completed		102B		\$9,749.96		Repair of rotating assembl
1	Electrical Work	On Going		103A				Orig budget \$25,000. Ele Sept 20th. Adjust for addit
1	SCADA Work	On Going		103A	\$7,000.00			Steve Rose and the SCA subscr to \$14k; Reduce pl
1	E-One Repairs and Replacement	On Going		103A				Orig budget: \$38,000. Bas replacement pumps; contr
1	Automatic Transfer Switch inspection and servicing	completed		101A		\$1,800.00		\$2400 - Annual Service pla
1	Wetwell Inspections and Cleaning - Plant/Pump Stations	On Going		103A	\$3,000.00			As required, plant or pump
1	Sewer Line Cleaning - Emergencies, pump & haul	On Going		103A	\$5,000.00			Placeholder - As required a or other, collection system
1	Collection System and plant - emerg & unplanned calls - Jetting & CCTV work - various contractors	On Going		103A	\$5,000.00			Budget - 15,000, 8/30 - re
1	Effluent Composite sampler	On Going		102B				Replace "tired" effluent con \$9760
3	Pump Station #5 jet lines to wetwell and WW cleaning	completed		103A				included with wetwell/colle
3	SHT1 - demo of equip, air piping & diffuser install/materials	Pending		103A				demo concrete in tank - \$1 equip \$6,000; air piping to project ?
4	Generators - Load Bank Testing Plant & Pump Stations	Pending		103A				Look at under 08M or 09M
1	Rosano Davis Pump & Haul PS9	completed		103A		\$28,800.00		for FM inspection
1	EESCO MCC work at the Pump Stations	Pending		103A				TBD 2 days - request for o
3	Low pressure sewer valve box insp & mtce	Pending		103A				placeholder for contractor another contractor & W&C
1	Est grit screw installation	Pending		102B	\$40,000.00			\$\$40,000 placeholder inst
1	Est Grit screw purchase	Pending		102B				placeholder hardware purc
1 3 of 4 3/14	AUMA actuator repairs & service	On Going		101A	2022 05 01 08M Check	pook YTD - Conv		PO# 105407 - issued for s

3/14/2023 14:11

Comments

s - charge is to 07M - estim \$3500. Wear shoe Items received July nal tail shaft assy and housing & bushings. Pricing out items/costs cl Mfr.

r complete unit. Under review/hold [est \$6,000].

mbly - at IPS shop. Returned in September 2022.

Electricians: Glen Fellows, HiVoltage, or other; adjust 8/30; adjust budget Idit exp 9/28; adj down on 11/28. Adjust to ZERO on 12/19/22.

CADA Support Team; budget \$20,000; Adj for cyber security protection placeholder budget to \$7,000.

Based on historica/recent costs. E1 repairs where cost-effective & new introl panels, other equip; Adjust 8/30. Adj 9/28 to Zero.

planned for NETS - Transfer Switch; Work comleted July 2022

imp stations; orig budget \$8,000; Update acct 9/28;

ed for various sub-contractors; could be Hoadley, Truax, WindRiver, BMC, em & plant; **budget \$10,000** Update acct 9/28;

reduce budget due to recent work; Update acct 9/28;

composite sampler. Waiting for PO to be issued. PO issued Dec 2022 for

ollection system work

 \$15,000 - sub-contractor and installation of new equip -additional new to the tank \$10,000; Total estimate: \$31k to 35K ??. Maybe year 09M

9M - recently done under 06M.

or quotation. Site visit done 10/27 by EESCO & waiting for proposal.

ctoror O&M inspections and potential repairs; Looking at Rosano-Davis or &C to investigate; budget of \$7,500 on hold

installation - TBD year 8 or year 9

ourchase. PO issued Oct 2022 \$48,122

Hull 2022-2023 - 08M Projects, Tasks, and Needs - (AV)								
Maintenance Account - Year 8 - 05_01_22 to 04_30_23								
	FOR January 2023 M.O.R.							
Priority [1=high]	Description	Status	completed	Task	Estimates & funds remaining	Final Completed Cost	Lead	
	HDWK fiberglass slide gate	Pending		101A	\$3,000.00			Soliciting estimates for at least
1	SC #2 Structural Steel Repairs	completed		103A	\$24,000.00			Based on T&M - center suppo
	TOTAL				\$125,337.00			

<u>3/14/2023 14:11</u>
Comments
ast one new slide gate. Placeholder [Jan 2023] \$3,000
ports, scrapers, other - IPC Lydon. Invoice pending